



# Minutes of 109<sup>th</sup> PCC Meeting

**Date: 04.01.2022**  
**Eastern Regional Power Committee**  
**14, Golf Club Road, Tollygunge**  
**Kolkata: 700 033**

## **EASTERN REGIONAL POWER COMMITTEE**

### **MINUTES OF 109<sup>th</sup> PROTECTION COORDINATION SUB-COMMITTEE MEETING HELD ON 16.12.2021 AT 10:30 HOURS**

Member Secretary, ERPC chaired the meeting. The meeting was convened through Microsoft Teams online platform.

List of participants is enclosed at **Annexure-A**.

#### **PART – A**

##### **ITEM NO. A.1: Confirmation of minutes of 108<sup>th</sup> Protection Coordination sub-Committee Meeting held on 16<sup>nd</sup> November 2021 through MS Teams online platform.**

The minutes of 108<sup>th</sup> Protection Coordination sub-Committee meeting held on 16.11.2021 was circulated vide letter dated 02.12.2021.

Members may confirm.

##### **Deliberation in the meeting**

*TPTL vide email dated 03.12.2021 had requested to include the following paragraph under the deliberation of agenda item No. B2 of 108<sup>th</sup> PCC meeting.*

“

*On 21st October 2021, Teesta III – Kishanganj line tripped due to landslide in the corridor which resulted in bringing the vegetation in the induction zone of the line. The landslide occurred due to extensive rainfall in the areas of Sikkim & West Bengal.*

”

*Members confirmed the minutes of the 108th PCC meeting with addition of above para with respect to the agenda item no. B2.*

#### **PART – B**

##### **ITEM NO. B.1: Disturbance at 220 kV Budhipadar S/s on 30.11.2021 at 10:12 Hrs**

On day of incident 220 kV Bus-1 at Budhipadar S/S was under shutdown. At 10:12 Hrs, Isolator dropper of 220 kV Budhipadar-Lephripada at Budhipadar snapped and created bus fault due to which 220 kV Bus-2 at Budhipadar tripped at Budhipadar which led to total loss of power in 220 kV side of 220/132 kV Budhipadar S/s.

220 kV IB TPS S/s became dead during the above incident.

Load Loss: 82MW, Gen. Loss: 348 MW  
Outage Duration: 00:23 Hrs

OPTCL may explain.

##### **Deliberation in the meeting**

OPTCL representative explained the disturbance as follows:

- 220 kV Bus-1 at Budhipadar S/S was under shutdown for annual maintenance work since 29.11.2021 and 220 kV Budhipadar -Lephripada feeder was charged through transfer bus coupler.
- On 30.11.2021 at 10:12 Hrs, during normalization of 220 kV Budhipadar-Lephripada from TBC to main bus, R phase isolator dropper snapped and created a bus fault in main bus-2.
- As the busbar protection is not in service, all the connected feeders got tripped from remote end in zone-2 timing to clear the fault.
- The disturbance led to total power failure at 220 kV Budhipadar S/s & 220 kV IB TPS station and islanding of Vedanta, Aditya Aluminium & Bhusan steel CPPs.

They clarified that the busbar protection was out of service due to faulty bay units of 220 kV Vedanta-1, Aditya Aluminium-1 & ATR-1 feeders. The matter is being taken up with OEM for restoration of the same.

On a query from PCC regarding assessment of healthiness of substation equipment and their replacement, they stated that their O& M team is assessing the healthiness of equipment of entire Budhipadar S/s and once the assessment gets completed, the cost estimate would be prepared and work order would be placed for replacement of old & defective equipment.

During analysis of the event, OPTCL informed that the zone-4 settings were not revised before shifting the feeders to main bus-2 which resulted in tripping of the feeders from remote end in zone-2 timing.

PCC opined that if bus bar protection is out of service for a particular bus, the zone 4-time settings for all feeders connected to that bus shall be revised to a reduced value (300 ms) and advised OPTCL to implement the same at Budhipadar S/s

PCC expressed serious concern on the matter of repeated disturbances at Budhipadar S/s and subsequent outage of 220 kV IB TPS generating units. The long delay in restoration of busbar protection at 220 kV Budhipadar is also a matter of concern which is affecting reliability & security of the grid. PCC decided to refer the matter to TCC meeting for due deliberation.

## **ITEM NO. B.2: Islanding performance assessment for Budhipadar disturbance on 30.11.2021**

### **A. Vedanta Islanding Event:**

#### **Chronology of Event:**

- At 10:12:31 hrs, Island was formed with tripping of 220 kV Budhipadar-Vedanta D/C circuits due to 220 kV bus fault at 220/132 kV Budhipadar substation.
- Vedanta was importing 20 MW from grid, so there was excess load of 20 MW after separation from grid. Hence in order to balance load, load shedding scheme tripped 2\*40 MW rectifier which led to total 80 MW of load tripping in the Vedanta Island.
- With tripping of 80 MW load, island became generation surplus of 60 MW, hence one unit went to house load (30-35 MW), which was earlier running at 125-130 MW. So, now the total excess load was approx. 40 MW in the islanded system.
- Out of 9\*135 MW units in Vedanta captive generation, one unit was under annual overhaul and one went to house load. So, now only 7 captive units were in service to provide governor action within the island. These units were already running near to full load so, adequate governor action provided by all units and load –generation was balanced in the island subsequent. Due to this, frequency was 50 Hz in the island.

- Frequency was steady at 50 Hz but it started decreasing after sustaining for 20 minutes due to reducing steam pressure, and some quantum of load picking meanwhile with manual action. This resulted in frequency to reach UFLS stg-2 which was set at 47.2 Hz for 1 second delay which caused tripping of load in the island via UFLS which could have been avoided if, some amount of load shedding could have been done in this duration.
- This load shedding led to higher frequency and caused further OFGS (Over frequency generation shedding) operation with frequency reaching 52.3 Hz for more than 500 ms that resulted in repeated phenomenon of UFLS & OFGS operation subsequently leading to collapse of islanded system.

#### **B. BHUSAN Islanding Event:**

- Bhusan was importing 60 MW from the grid prior to event at Budhipadar substation.
- 130 MW X 3 Units got islanded, however it did not survive as Unit 1 & 3 tripped within 2 second and Unit 2 tripped after 8 seconds. As per the islanding scheme it should survive with house load at 33 kV.
- 60 MW unit in the Bhushan steel got islanded and went to house load with 15 MW of load.

#### **C. Aditya Aluminium Islanding Event:**

Prior to islanding flow was almost floating, after islanding it survived.

Detailed report is attached at **Annexure B.2.**

Concerned CPPs may explain.

#### **Deliberation in the meeting**

*ERLDC representative explained the islanding events of the CPPS during the disturbance at Budhipadar S/s on 30.11.2021.*

##### **a) Vedanta Islanding Scheme**

- *The Island was formed after tripping of 220 kV Vedanta- Budhipadar circuits. Prior to tripping, Vedanta was importing 20 MW of power from grid so excess load was of 20 MW. In order to balance load and generation, load shedding scheme operated and tripped 2\*40 MW rectifier.*
- *After tripping of 80 MW load, island became generation surplus by 60 MW. Subsequently one unit went to house load (30-35 MW), which was running at 125-130 MW. Excess load in the island became around 40MW.*
- *Out of 9\*135 MW units, one was under annual overhaul and one went to house load, the rest seven units were in service to provide governor actions and units were already running near full capacity so full governor action was done by all units and load –generation got balanced due to which frequency was steady around 50 Hz however it started decreasing after sustaining for 20 minutes due to reducing steam pressure and due to some quantum of load picking.*
- *Meanwhile with manual action subsequently frequency reached UFLS stg-2, 47.2 Hz @1sec which further caused OFGS (Over frequency generation shedding), 52.3Hz @500ms, and repeated phenomenon of UFLS & OFGS ultimately caused collapse of islanding scheme.*

*The following observations were made from the analysis of the event:*

- While the excess load was 20 MW in the island, the load shedding was done to the tune of 80 MW which as a result creates a generation surplus of 60 MW. The load shedding scheme may be reviewed.
- While steam pressure was reducing, some amount of load shedding in the island could have been done to avoid UFLS operation and subsequent island collapse.
- Sluggish response of governor had resulted in repeated phenomenon of UFLS & OFGS which was the reason behind non-survival of islanding scheme.

Vedanta representative submitted that the root cause for non-survival of islanding was being analyzed by them. They informed that during the incident there was voltage drop in islanded system because of which most of auxiliary got tripped in undervoltage protection subsequently compressors got tripped resulting in non-survival of island.

They further informed that load shedding scheme is being reviewed in consultation with OEM of the units.

PCC advised Vedanta to implement a revised load shedding scheme as well as to tune the governor responses of the CPP units for ensuring survival of the island.

#### **b) Bhusan Islanding Scheme-**

- Prior to incident, 2\*40 MW units were under Shutdown and Bhusan was importing 60 MW from Grid.
- It was informed that 3\*130 MW Units got islanded after the disturbance however the island did not survive as unit# 1&3 tripped within 2 second and unit 2 tripped after 8 seconds.
- The 60MW unit got islanded and went to house load with 15 MW of load.

PCC advised Bhusan CPP to submit a report regarding non-survival of their islanded system and action taken thereof.

#### **c) Aditya Aluminium Islanding Scheme-**

It was informed that Aditya Aluminium Island survived after tripping incident at Budhipadar S/S.

#### **ITEM NO. B.3: Multiple tripping at 220/132 kV Jayanagar (OPTCL) Substation on 04.11.2021.**

At 10:11 Hrs on 04.11.2021, following elements tripped at 220/132 kV Jaynagar substation

Sl.No.	Name of the feeder	Trip Time/Date	Restoration time/Date	Local end	Remote end
1	220 KV Jayanagar-Upper Kolab-1	10:19 Hrs, 04-11-2021	12:12/ 04.11.2021	Tripped with Z-2, Dist- 5.87KM, fault current IA- 6.929 KA	Tripped on Z-1, Dist- 3.5KM, IA- 2.89KA

2	220 KV Jayanagar- Jeypore(PGCIL ) -3		12:05/ 04.11.2021	Tripped on 86A, 86B	Didn't trip at PGCIL end.
3	220 KV Jayanagar- Jeypore(PGCIL)- 4		12:09/ 04.11.2021	Tripped on 86A, 86B.	Didn't trip at PGCIL end
4	132KV Jayanagar- Meenakshi		11:03/ 04.11.2021	Tripped without relay indication.	Tripped on Z-III, Dist-120.6KM, B- Ph O/C

### Event Analysis:

- Fault was in 220 kV Jayanagar-Upper Kolab-1 which was detected in Zone-2 from Jaynagar end and Zone-1 from upper kolab end. Since PLCC is unhealthy fault was cleared in Zone-2 time from Jayanagar end.
- 220 kV Jeypore-Jayangar-3 & 4 are newly commissioned lines where due to wrong logic tripping occurred from Jayanagar end which is already rectified. Carrier was unhealthy at tripping instance at OPTCL end.
- 132KV Jayanagar-Meenakshi feeder tripped in zone -3.

Detailed report is attached at **Annexure B.3**.

OPTCL may explain.

### Deliberation in the meeting

*OPTCL representative informed that the fault was in 220 kV Jayanagar-Upper Kolab-1 line near to upper Kolab end. The relay at Upper Kolab end sensed the fault in zone-1 protection and cleared the fault instantaneously whereas the line tripped from Jayanagar end in zone-2 timing. They stated that the PLCC was not in healthy condition at the time of disturbance which resulted in zone-2 tripping from Jayanagar end.*

*Regarding tripping of 220 kV Jeypore-Jayangar-3 & 4 line during the above disturbance, he explained that the lines were recently commissioned and PLCC was not working for the lines at the time of disturbance. As per the logic implemented in the relay, the master trip relay would operate when any trip with A/R block and carrier unhealthy condition gets satisfied. This resulted in tripping of both the feeders from Jaynagar end though the relay sensed the fault in reverse zone.*

*They informed that the logic had been modified to zone-1 trip instead of any trip and the same had been implemented in the relay.*

*It was further informed that 132 kV Jayanagar-Meenakshi line also sensed the fault in zone 3 and tripped from Meenakshi end. OPTCL was advised to take up the matter with Meenakshi end for necessary review of zone settings at Meenakshi end.*

*Regarding present status of PLCC for 220 kV Jayanagar-Upper Kolab-1 line and 220 kV Jeypore-Jayangar-3 & 4 lines, OPTCL submitted that carrier is healthy at Jayanagar end for all the above lines.*

#### ITEM NO. B.4: Bus tripping occurred in Eastern Region during November 2021

During November 2021 following incidents of bus bar tripping have been observed in Eastern Region.

Element Name	Tripping Date	Reason	Utility
400 kV Main Bus-1 at FSTPP	04-11-2021 at 09:40 Hrs	CB of 400 kV FSTPP-Durgapur-2 stuck at FSTPP. LBB operated.	Farakka NTPC
400 kV Main Bus-1 at New Purnea	15-11-2021 at 10:20 Hrs	Due to spurious LBB signal during s/d of 400 kV New Purnea-Binaguri-1 & 2	PG ER-1
400 kV Main Bus-2 at Jeypore	30-11-2021 at 10:41 Hrs	Tripped due to mal-operation	PG Odisha Projects

NTPC, Powergrid ER-1 & Powergrid Odisha may explain.

#### **Deliberation in the meeting**

##### **400 kV Bus-1 at FSTPP:**

*NTPC representative explained that there was fault in 400 kV FSTPP-Durgapur circuit-2 for which tripping command was issued by the relay at Farakka end. However, the circuit breaker for the above feeder got stuck and the breaker did not open. As a result LBB protection operated and tripped all the feeders connected to 400 kV Main Bus-1 of FSTPP.*

##### **400 kV Main Bus-1 at New Purnea:**

*Powergrid representative explained that the disturbance occurred while availing shutdown of 400 kV New Purnea-Binaguri-2 line. The line was initially opened from Binaguri end and subsequently the DT signal was transmitted to New Purnea end.*

*Upon receiving of the DT signal, the LBB protection initiated at new Purnea end. However, due to faulty relay, the current signal did not get reset and remained high though there is no current in the line. As a result, LBB operated and tripped main bus-1 elements at New Purnea end.*

*They stated that the fault relay was replaced on the same day.*

##### **400 kV Bus-2 at Jeypore S/s:**

*Powergrid representative explained that while adjusting mechanical interlock between isolator and earthswitch of a feeder, the isolator leg moved undesirably and caused sparking at isolator. Since the earth switch was in closed condition, the event resulted into a bus fault and busbar protection operated for 400 kV bus-2 of Jeypore S/s.*

#### ITEM NO. B.5: Repeated Spurious Tripping of 400 kV Barh-Patna-1

400 kV Barh-Patna-1 had tripped on three occasions on Direct Trip (DT) receipt at Barh end whose details are as follows-

>	400KV-PATNA-BARH-1	13/11/2021	08:36	DT recieved at Barh.No trip at Patna end		13/11/2021	09:58
>	400KV-PATNA-BARH-1	13/11/2021	04:09	Barh: DT recieved, 86 relay operated Patna: Not Tripped		13/11/2021	04:45
>	400KV-PATNA-BARH-1	08/11/2021	13:57	TRIPPED FROM ONLY BARH END		08/11/2021	14:49

NTPC and Powergrid may explain.

### **Deliberation in the meeting**

*Powergrid representative informed that during investigation it was found that spurious DT signal was being generated from channel 1 of PLCC panel at Barh end which caused tripping of 400 kV Barh-Patna-1 line.*

*They further informed that OEM engineers had visited the site however the issue could not be rectified by them. Further R&D team of OEM has been scheduled to visit the site to analyze and rectify the issue.*

*They stated that channel 1 of PLCC had been disconnected at Barh and intimation was given to ERLDC.*

### **ITEM NO. B.6: Protection Audit in Eastern Region**

Protection audit is a primary activity to ensure power system protection implemented at substations and power plants are well coordinated and is as per CEA standards. Due to COVID-19, the activity could not be started since March 2020. Since then, various events have occurred where issues of protection coordination have been observed and several new substation and grid element has been connected with the grid. Therefore, it is now prime requirement to re-commence protection audit of substations and power plants in the Eastern Region. In view of this, following activities have been decided to streamline the audit process:

#### **PCC activities**

- Formation of Three-Four core audit teams-All utilities to nominate their members
- Nodal officer from all utilities to co-ordinate with audit activities
- Identification of S/s to be audited
- Finalization of audit format

#### **Pre-audit activities**

- Utilities of S/s thus identified to check and update latest protection settings in PDMS database within next 7 days
- S/s to fill up pre-requisite data as per format attached before visit of audit team

#### **Input to be obtained from protection database**

- SLD of the S/s
- List of elements
- Updated settings from PDMS database (PDF/excel)
- Model setting for the elements of substation being audited

#### **On the day of Audit at Substation/Plants**

- Verification of protection setting as per details provided.



- All testing reports
- Equipment's healthiness status, DC healthiness, Aux system healthiness etc.

Audit team observation will be shared with utilities and in PCC for action plans and compliance monitoring.

Format for protection audit checklist is attached at **Annexure B.6**.

Members may discuss.

### **Deliberation in the meeting**

*ERPC Secretariat representative briefed about the third-party protection audit activities which were carried out in Eastern Region in the past and its requirement vis-à-vis the benefits. He informed that protection audit for ER substations could not be carried out since the onset of Covid Pandemic. The last comprehensive audit for all 400 kV & 220 kV substations in ER were carried out long ago and in between a number of new 400 & 200 kV substations has been commissioned.*

*In view of above it was proposed to recommence the protection audit activity in ER. The audit would cover all 400 kV & 220 kV Substations in Eastern Region including the power plant substations.*

*The audit procedure was outlined in the agenda the same was elaborated in the meeting.*

- *It was informed that 3-4 audit team will be constituted consisting members from state utility, central utility, ERLDC & ERPC secretariat. The list substations where the audit is to be carried out would be finalized beforehand in PCC meeting and the concerned utility needs to check and update the relay/protection settings available in the protection database (PDMS) before the field visit. Further the nodal officer has to coordinate with the audit teams to facilitate their visit in carrying out the substation audit.*
- *The audit team would submit their report and observation to ERPC secretariat and the same would be placed in PCC meeting for information and compliance, if any, by the auditee utility.*

*Members agreed to the proposal of requirement of periodic protection audit for the substations and expressed their full cooperation in the audit activities.*

*PCC advised utilities to submit their comments, if any, regarding the procedure and format to be followed for carrying out the protection audit.*

*PCC also advised all state utilities including state generating utility, DVC, Powergrid, NTPC & NHPC to nominate at least 2-3 members from their organization who are looking after system protection/testing related work for constitution of audit teams. Separately a nodal officer may be nominated for each utility to coordinate the audit activities for the substations in their system.*

### **ITEM NO. B.7: Tripping Incidence in month of November 2021**

Tripping incidents in the month of November 2021 which needs explanation from constituents of either of the end is attached.

Concerned utilities may explain.

### **Deliberation in the meeting**

*Explanation from constituents related to tripping incidents in the month of November 2021 is attached at **Annexure B.7**.*

## **PART- C::OTHER ITEMS**

### **ITEM NO. C.1: Requirement of additional MiP-PSCT License key with Laptop**

44thTCC advised all the utilities of ER including JUSNL to furnish their requirement, if any, for additional MiP-PSCT license to ERPC Secretariat citing proper justification.

Further in 44<sup>th</sup>ERPC meeting, ERPC advised all the utilities to submit their requirement, if any, by 15th October'2021. ERPC further advised ERPC Secretariat to prepare and submit a DPR for additional MiP-PSCT licenses required for ER utilities for PSDF funding.

In 106<sup>th</sup> PCC meeting, PCC advised concerned utilities to submit their additional requirement of PSCT license, if any, to ERPC secretariat within fifteen (15) days.

The requirement for additional MiP-PSCT license key had been received from SLDC Odisha, JUSNL & WBSETCL.

*In 108<sup>th</sup> PCC Meeting, ERPC informed that requirement for additional MiP-PSCT license key was received from SLDC Odisha, JUSNL & WBSETCL.*

*PCC advised remaining utilities to submit their additional requirement of PSCT license, if any, to ERPC secretariat within fifteen (15) days*

Members may discuss.

### **Deliberation in the meeting**

*ERPC secretariat informed that requirement for additional MiP-PSCT license key was received from SLDC Odisha, JUSNL, WBSETCL & BSPTCL.*

*It was further informed that DPR preparation w.r.t the above work had already been initiated and after finalization of DPR, the same would be submitted to PSDF nodal agency.*

### **ITEM NO. C.2: List of works carried out by PRDC Pvt. Ltd. during the period of November 2020 to October, 2021.**

The Protection Database project has been implemented by PRDC and declared "Go Live" on 31st October, 2017. In continuation to above, PRDC submitted report for verification of works carried out during the period of November, 2020 to October, 2021.

PRDC may present. Members may discuss.

### **Deliberation in the meeting**

*PRDC gave detailed presentation on works carried out by them during the period of November, 2020 to October, 2021 which is attached at **Annexure C.2**.*

*Members noted.*

### **ITEM NO. C.3: Follow-up of Decisions of the Previous Protection Sub-Committee Meeting(s)**

The decisions of previous PCC meetings are attached.

Members may update the latest status.

#### **Deliberation in the meeting**

*Updated status for decisions of previous PCC meetings is given at **Annexure C.3**.*

### **ITEM NO. C.4: Implementation of Differential protection for shorter lines**

As per the CEA standard, transmission line protection can have either have distance or differential protection scheme as main protection scheme. It has been observed that for short lines distance protection scheme tends to over reach and pose protection coordination issues with other elements from the substation. Further many a times due to this short line distance protection the longer lines from remote ends have to increase their zone-2-time delays to higher values (500-600 ms).

In view of this inherent issue the REPORT OF THE TASK FORCE ON POWER SYSTEM ANALYSIS UNDER CONTINGENCIES recommends the following:

*LINE DIFFERENTIAL PROTECTION- Many transmission lines are now having OPGW or separate optic fiber laid for the communication. Where ever such facilities are available, it is recommended to have the line differential protection as Main-I protection with distance protection as backup (built-in Main relay or standalone). Main-II protection shall continue to be distance protection. For cables and composite lines, line differential protection with built in distance back up shall be applied as Main-I protection and distance relay as Main-II protection. Auto-recloser shall be blocked for faults in the cables.*

Based on the above in the 68th PCC ER forum members agreed on:

*PCC opined that differential protection should be implemented for all short lines (<20 kM) to overcome relay coordination issues with respect to distance and over current protection.*

In view of the above, the status of implementation differential protection for shorter lines in the eastern region may be followed up at ER PCC forum level.

A list of short lines (< 20 Km) at 220 kV and above voltage level is attached at **Annexure C.4**.

Members may discuss.

#### **Deliberation in the meeting**

*PCC enquired about the criteria adopted by utilities for implementing line differential protection in the lines at 220 kV and above level.*

*The views of utilities are given below:*

- WBSETCL representative informed that as per their adopted practice criteria of line length < 10 km is considered for implementing line differential protection. For line length > 10 km, distance protection scheme gives satisfactory results as such they do not require implementing line differential protection for line length of 10-20 km.
- DVC representative informed that they had considered the criteria of line length < 10 km for implementing line differential protection scheme in their system.
- ERPC secretariat opined that in general for very short lines having line length less than 10 km, limitations are imposed by R/X of the relay in accurate setting of zone-1 of distance protection so the criteria of implementing line differential protection for line length of less than 10 km may be adopted by the utilities for lines at 220 kV & above voltage level. However, in critical and important lines as recommended by PCC forum, utility shall provide line differential protection irrespective of length of line. Members agreed to the above proposal.

Regarding status of implementation of differential protection for existing short lines in Eastern Region, PCC advised BSPTCL, OPTCL, DVC & WBSETCL to submit the required details for the lines as listed in the annexure. Further PCC advised all the utilities to furnish the list of the lines where line differential has been proposed for implementation over and above the list of lines mentioned in the annexure.

JUSNL informed that line differential scheme is present in both 220 kV Chaibasa-Chaibasa (JUSNL) D/c & in 220 kV Ranchi-Hatia line.

Regarding 220 kV Rangpo-Rongnichu D/C line, Rongnichu informed that OPGW carrier communication is available in the line and the relays have facility for implementing differential protection. PCC advised Powergrid & Rongnichu HEP to implement line differential protection for the line.

Similarly, for 400 kV Rangpo-Teesta V D/C line, NHPC stated that OPGW carrier communication is present in the line. PCC advised Powergrid to implement line differential protection for 400 kV Rangpo-Teesta V line.

For other 400 & 220 kV lines in the Sikkim complex, line differential protection would be implemented after commissioning of OPGW communication link.

#### **ITEM NO. C.5: New Element Integration**

As per information received at ERLDC, 400 kV Kahalgaon (KhSTPP)-Durgapur-2 is going to be first time charged. This circuit is a reconfiguration of 400 kV Farakka (FSTPP)-Kahalgaon (KhSTPP)-4 and 400 kV Farakka (FSTPP)-Durgapur-2 bypassing Farakka substation.

Its modified line parameter as provided below as received from the PGCIL:

Name	Conductor type	Length
------	----------------	--------

400 kV Kahalgaon (KhSTPP)-  
Durgapur-2

ACSR Twin Moose

242.941 km

In view of this, Protection coordination may be required as per the following table (Based on information available at ERLDC):

Reason	Settings to be reviewed for	Settings to be reviewed at substation	Utility	Remarks
FTC of 400 kV Kahalgaon (KhSTPP)-Durgapur-2 (Bypass near Farakka)	400 kV Kahalgaon (KhSTPP)-Durgapur-2	KhSTPP, Durgapur	NTPC KhSTPP , PG ER-2	Protection coordination to be done for newly connected element as per ERPC guidelines.
	400 kV Farakka (FSTPP)-Kahalgaon-1,2,3	FSTPP	NTPC FSTPP	Adjacent longest line for these lines will now be 400 kV Kahalgaon-Durgapur-2 (242.941 km). Hence Zone-3 settings at respective S/s may be reviewed keeping in view it should not encroach next voltage level. Kindly check and confirm any setting revision if any change in adjacent short and long line.
	400 kV Maithon A-Kahalgaon (KHSTPP)	Maithon A	PG ER-2	
	400 kV Maithon B-Kahalgaon (KHSTPP)	Maithon B	PG ER-2	
	400 kV Barh-Kahalgaon D/c	Barh	NTPC Barh	
	400 kV Banka-Kahalgaon D/c	Banka	PG ER-1	
	400 kV Lakhisarai-Kahalgaon D/c	Lakhisarai	PG ER-1	
	400 kV Maithon-Durgapur A D/c	Maithon	PG ER-2	
	400 kV Sagardighi-Durgapur B D/c*	Sagardighi	WBPDC L	
	400 kV Bidhannagar-Durgapur B D/c*	Bidhannagar	WBSET CL	
	400 kV Farakka (FSTPP)-Durgapur B (Ckt-1)*	FSTPP	NTPC FSTPP	
	400 kV Jamshedpur-Durgapur B*	Jamshedpur	PG ER-1	
	* Setting for the scenario when bus coupler at 400/220 kV Durgapur S/s is in closed condition. At present, bus coupler is in closed condition however in future it will be opened when desired changes at Durgapur substation are in place as per bus split plan decided in previous ERPCTP MoM.			

In future, when Bus coupler at Durgapur will be kept open, Then Zone-3 setting of following lines may need to be reverted back to present setting in future:

Settings to be reviewed in	S/s to change	Utility
400 kV Sagardighi-Durgapur B D/c	Sagardighi	WBPDC L
400 kV Bidhannagar-Durgapur B D/c	Bidhannagar	WBSETCL
400 kV Farakka (FSTPP)-Durgapur B (Ckt-1)	FSTPP	NTPC FSTPP
400 kV Jamshedpur-Durgapur B	Jamshedpur	PG ER-1

**Following details to be shared:**

- Respective utilities may share whether revision of any existing protection setting at above mentioned S/S is required or not. In case of any revision, the revised setting may be shared with ERPC and ERLDC. All revisions may be carried out as per ERPC protection philosophy.
- Status of carrier protection and PLCC channel in the all above mentioned section to be ensure and same may be shared.
- Utilities should ensure that proper protection coordination are in place after charging of these lines/elements.

Members may update.

**Deliberation in the meeting**

*PCC advised concerned utilities to confirm their protection coordination to ERLDC/ERPC.*

## LIST OF PARTICIPANTS IN 109TH PCC MEETING HELD ON 16TH December 2021

Full Name	Join Time	Email
ERPC Kolkata	12/16/2021, 10:10:31 AM	ERPC@KolkataMST.onmicrosoft.com
Amresh Mallick	12/16/2021, 10:21:54 AM	amareshmallick@erldc.onmicrosoft.com
DEBDAS MUKHERJEE WBPDC (Guest)	12/16/2021, 10:23:28 AM	
SMS SAHOO,DGM,OPTCL,BHUBANESWAR (Guest)	12/16/2021, 10:25:42 AM	
Satya Deep Tangudu (Dikchu H.E.P) (Guest)	12/16/2021, 10:27:01 AM	
Teesta-V Power Station (Guest)	12/16/2021, 10:27:18 AM	
Amresh Prusti	12/16/2021, 10:27:36 AM	amresh.prusti@opgc.co.in
Mk Rath	12/16/2021, 10:28:07 AM	
PGCIL ER1	12/16/2021, 10:29:05 AM	
Gulshan Singh	12/16/2021, 10:30:17 AM	
Arindam Bsptcl	12/16/2021, 10:30:45 AM	
U K MISHRA (Guest)	12/16/2021, 10:30:46 AM	
GAUTAM NAYAK (Guest)	12/16/2021, 10:30:48 AM	
SLDC-ODISHA (Guest)	12/16/2021, 10:31:08 AM	
Ch Mohan Rao,PG,Odisha	12/16/2021, 10:32:29 AM	
Ajay Majhi	12/16/2021, 10:32:38 AM	ajay.majhi@opgc.co.in
GULSHAN SINGH MBPCL Rongnichu HEP (Guest)	12/16/2021, 10:33:15 AM	
Ankur Kumar (Guest)	12/16/2021, 10:33:39 AM	
Jaganath Pani	12/16/2021, 10:34:34 AM	
Mangu Srinivas	12/16/2021, 10:34:39 AM	211321@vedanta.co.in
Jaganath Pani NHPC	12/16/2021, 10:35:07 AM	
Sudhakar Swain	12/16/2021, 10:36:36 AM	
CRITL	12/16/2021, 10:36:37 AM	
EMR MERAMUNDALI (Guest)	12/16/2021, 10:37:55 AM	
Alok Pratap Singh ,ERLDC (Guest)	12/16/2021, 10:38:16 AM	
Akash Modi, ERLDC (Guest)	12/16/2021, 10:39:51 AM	
Akash Kumar Modi	12/16/2021, 10:40:43 AM	akmodi@erldc.onmicrosoft.com
Ganesh Korada	12/16/2021, 10:41:35 AM	ganesh.korada@opgc.co.in
jitesh kumar (Guest)	12/16/2021, 10:41:36 AM	
D.PATEL OPTCL EMR MERAMUNDALI	12/16/2021, 10:41:41 AM	
P P CHAND (ERLDC) (Guest)	12/16/2021, 10:42:46 AM	
TVNL (Ashish Kr Sharma) (Guest)	12/16/2021, 10:46:34 AM	
DILSHAD ALAM	12/16/2021, 10:46:44 AM	
Rajdeep Bhattacharjee, RE, BSPHCL, Kolkata	12/16/2021, 10:48:04 AM	admin@BSPHCL317.onmicrosoft.com
Abinash Panigrahi	12/16/2021, 10:50:26 AM	abinash.panigrahi@adityabirla.com

TEESTA-III (Guest)	12/16/2021, 10:51:07 AM	
NHPC Teesta-V Power Station (Guest)	12/16/2021, 10:51:15 AM	
rajendra prasad (Guest)	12/16/2021, 10:52:03 AM	
Sukdev (PG) (Guest)	12/16/2021, 10:54:17 AM	
Madan Prasad	12/16/2021, 10:55:30 AM	
p chatterjee	12/16/2021, 10:56:41 AM	
Sudipta Maiti DVC (Guest)	12/16/2021, 10:57:18 AM	
A D Balde	12/16/2021, 10:58:35 AM	
"prabhat k (TPTL) (Guest)	12/16/2021, 11:01:07 AM	
Pallavi Kansal	12/16/2021, 11:01:15 AM	pallavi.k@tvptl.com
MS ERPC, N S MONDAL (Guest)	12/16/2021, 11:02:39 AM	
Sankhadeep Choudhury (Guest)	12/16/2021, 11:04:24 AM	
Bauribandhu Behera	12/16/2021, 11:07:18 AM	bauribandhu.behera@opgc.co.in
Kurshna samntray	12/16/2021, 11:08:11 AM	krushna.samantray@opgc.co.in
RAHUL KUMAR	12/16/2021, 11:11:27 AM	
shadab hasan	12/16/2021, 11:15:54 AM	
PRAFULLA KUMAR Satapathy	12/16/2021, 11:19:44 AM	
rajeevranjan.mit06@gmail.com	12/16/2021, 11:20:13 AM	
Satyapriya Behera	12/16/2021, 11:39:46 AM	satyapriya.behera@opgc.co.in
abhishek kumar BSPTCL	12/16/2021, 11:47:33 AM	
Dharm Das Murmu, CRITL, JUSNL (Guest)	12/16/2021, 11:47:58 AM	
GULSHAN SINGH MBPCL (Guest)	12/16/2021, 11:53:04 AM	
eee critl	12/16/2021, 12:07:40 PM	
Jaganath Pani NHPC	12/16/2021, 12:37:42 PM	
RTAMC PATNA (Guest)	12/16/2021, 12:45:39 PM	
P	12/16/2021, 1:06:45 PM	
Alok ERLDc	12/16/2021, 1:08:04 PM	
Ch Mohan Rao	12/16/2021, 1:21:16 PM	
Amit Kumar	12/16/2021, 1:21:32 PM	
Rajiv Kumar Singh CESC	12/16/2021, 1:47:26 PM	




## ISLANDING PERFORMANCE ASSESSMENT FOR BUDHIPADAR DISTURBANCE

### Summary of the event:

At 10:12 Hrs, 220 kV Bus-2 at Budhipadar tripped (220 kV Bus-1 was under shutdown), leading to total power failure in 220 kV side of 220/132 kV Budhipadar S/s, 220 kV IB Thermal. There are three captive plants in vicinity-Vedanta, Bhushan Steel and Aditya Aluminium. Vedanta island survived for 22 minutes. Bhushan Steel Island didn't survive. Aditya Aluminium island survived. Total 348 MW generation loss occurred at IB TPS, and 82 MW load loss occurred (supply to Vedanta, Bhushan and Aditya Aluminium CPP).

### Vedanta Islanding Event:

Frequency plot from Scada data for the event shown below. (See the plot from left to right)




### Chronology of Event:

- At 10:12:31 Island formed with tripping of Budhipadar circuits.
- 20 Mw was import from grid, so excess load was of 20 Mw, hence to balance that ,load shedding scheme tripped 2\*40 Mw rectifier so total 80 Mw of load tripped . **(See the plots attached below).**
- With tripping of 80 Mw load, island became generation surplus of 60 Mw , hence one unit went to house load(30-35 Mw) , which was running at 125-130 Mw .So total excess load was approx 40Mw.
- Out of 9\*135 Mw units one was under annual overhaul, one went to house load so only 7 units were in service to provide governor action.
- Units were already running near to full so, full governor action came by all units and load – generation was balanced and frequency was 50 Hz as shown below.
- Frequency was steady at 50 hz but it started decreasing after sustaining 20 minutes due to reducing steam pressure , and due to some quantum of load picking meanwhile with manual action .This caused frequency to reach UFLS stg-2 ,47.2 [Hz@1sec.](#) **(If during this duration some**


amount of load shedding could be done this may have avoided the slow drop in frequency, some mechanism can be put to ensure the same).

- This caused further OFGS (Over frequency generation shedding) ,52.3Hz@500ms, and same repeated phenomenon of UFLS & OFGS ultimately caused island collapse. (This sudden UFLS AND OFGS Suspected cause for this is the sluggish response of governor which was unable to cope-up with with load –generation imbalance instantaneously).
- Steam valve opening is sluggish which needs to be attended and rectified for successful islanding in future events. A co-ordinated governor tuning of all units in islanded mode may be done by Vedanta in this regard to take prompt action for ensuring the successful islanding.

Plot of Frequency Data received from Vedanta: Starting of ISLAND & associated dynamics: (See the plot from right to left)



Before ISLAND collapse & associated dynamics: : (See the plot from right to left)



### BHUSAN Islanding Event:

- Bhusan was importing 60 Mw from Grid prior to Event.
- 130 Mw\*3 UNIT islanded and did not survived, Unit 1&3 tripped within 2 second and Unit 2 tripped after 8 Seconds. As per the islanding scheme it should survive with house load at 33kv.
- 60Mw unit islanded and went to house load with 15 Mw of load.
- 2\*40 Mw unit were under Shutdown.
- **Detailed analysis for root cause of Non-survival is pending and remedial measures to be taken to ensure successful islanding.**

### Aditya Aluminium Islanding Event:

- Prior to islanding flow was almost floating, after islanding it survived.

## Root Cause Analysis for multiple tripping at Jeynagar

Following tripping's occurred on 04 th November .

Sl. No.	Name of Grid S/S	Name of the feeder	Trip Time/ Date	Close time/Date	Duration	Relay Indication	
						Local end	Remote end
1	220/132/33KV GSS ,Jayanagar	220 KV Jayanagar- Upper Kolab ckt-I	10:19/ 04.11.2021	12:12/ 04.11.2021	01:53 min.	Tripped with Z-2, Dist- 5.87KM, fault current IA- 6.929 KA	Tripped on Z- 1, Dist- 3.5KM, IA- 2.89KA
2		220 KV Jayanagar- Jeypore(PGCIL )ckt- III	10:19/ 04.11.2021	12:05/ 04.11.2021	01:46 min.	Tripped on 86A, 86B	Didn't tripped at PGCIL end.
3		220 KV Jayanagar- Jeypore(PGCIL )ckt- IV	10:19/ 04.11.2021	12:09/ 04.11.2021	01:50 min.	Tripped on 86A, 86B.	Didn't tripped at PGCIL end
4		132KV Jayanagar- Meenakshi feeder	10:19/ 04.11.2021	11:03/ 04.11.2021	00:44 min.	Tripped without relay indication.	Tripped on Z- III, Dist- 120.6KM, B- Ph O/C

### Antecedent Condition:

- 220 kv Jeypore – Jeynagar III& IV newly commissioned line.
- At the time of disturbance Carrier was unhealthy for Jeypore – Jeynagar ckt 3&4.
- 220 kv Jaynagar-Upper kolab Carrier was unhealthy.

### Event Analysis:

- Fault was in 220 kv Jaynagar-Upper kolab –I , in Zone-2 from jaynagar and z-1 from upper kolab but as the PLCC is unhealthy it tripped after zone 2 time from jeynagar.
- 220 KV Jayanagar-Jeypore(PGCIL ) III &iv are newly commissioned where wrong logic was set for tripping which caused tripping of these two circuits . **Carrier was unhealthy for both the lines at the tripping instance.**
- **(Logic implemented should be operation of MASTER TRIP 86 A &B when zone-1 trip with A/R block and carrier unhealthy)** but instead of zone-1 trip ,**any trip was enabled in logic** , due to which for the fault of Jeyanagr –upper kolab ,zone-4 at Jeynagar end of Jeynagar –jeypore 3&4 was picked up and as per the wrong logic, any start high along with carrier unhealthy caused tripping of both circuit from Jeynagar.
- 132KV Jayanagar-Meenakshi feeder tripped on zone -3 which should not occur as fault was cleared within zone-2 time , zone-3 timing to be checked and revised at meenakshi end which has been communicated to OPTCL.

### Remedial Measure:

- Same has been rectified and logic changed to zone-1 instead of any trip.
- Carrier healthiness to be ensured for all lines.
- OPTCL communicated to change zone-3 settings at Meenakshi end.

## PROTECTION AUDIT REPORT

### General information

Substation name: .....

SS voltage level: .....

Fault level of all equipment  
(for that voltage level) .....

Date of commissioning  
of the substation: .....

Region: .....

Audit date: .....

Name of utility which owns the  
substation (e.g POWERGRID,  
MSETCL, ADANI POWER, etc.) .....

### Audit Team

Name	Company name
.....	.....
.....	.....

### Regional representatives:

Name	Company name
.....	.....
.....	.....
.....	.....
.....	.....
.....	.....
.....	.....
.....	.....
.....	.....

### Attached documents:

- 1 List of the faults that was/were not eliminated by the protection; .....
- 2 Record of previous trippings for last six months and associated fault analysis. ....
- 3 Single/three pole auto-recloser events, if any in last six months; .....
- 4 Details on periodicity of relay testing and latest relay test report .....
- 5 Communication from concerned department for the revised settings and record for implementation of  
the revised settings. ....
- 6 CT characteristics at all taps in case of multi-ratio CTs .....
- 7 df/dt, UFR relay details and settings if its available .....
- 8 Special Protection Schemes details if applicable. (Including test results & last operation records),  
implemented schematic diagram for SPS .....
- 9 Single Line Diagram .....

## CONCLUSIONS OF PROTECTION AUDIT REPORT

Item no.	Issues	Remarks
1	Recommendations of last Protection Audit	Status of works&reason for pending/suggestions
2	Review of Existing Settings at Substations	
	Any inadvertently enabled settings/functions observed. (Yes/No)	
3	Disturbance recorder - list of 3 trippings in last 6 months	Recommended action
3.a	DR as well as EL records for the trippings available (Yes/No)	
3.b	Records available for Tripping analysis and corrective actions taken (Yes/no)	
3.c	Time Synch Matched Between EL signals and DR signals (Yes/No)	
3.d	Digital Signals of DR named properly (main CB Trip, Z1 Trip etc.) (Yes/No)	
4	Chronic reason of tipping, if any	Recommended action

Item no.	Issues	Remarks
5	Existing process for record of changes incorporated in the relay settings	See attached corespondence
6	Overvoltage grading for parallel line (time&pick up grading, provided or not)	Recommended action
7	Other deficiencies/Nonconformity observed (including the major non-conformaties mentioned in the audit format. ex: Single AC source etc.)	Recommended action

## Appendix-9.4

### CHECK LIST TO ENABLE AUDIT OF PRACTICES FOLLOWED IN PROTECTION APPLICATION & CRITERIA USED FOR SETTING CALCULATIONS IN 220KV, 400KV & 765KV SUBSTATIONS

**CHECK-LIST:** Check list for different protected objects & elements in fault clearance system are as under:

(put  $\checkmark$  mark in the appropriate box )

#### A. Transmission Lines (OHL and Cables)

1.	Independent Main-I and Main-II protection (of different make OR different type) is provided with carrier aided scheme	<input type="checkbox"/> YES <input type="checkbox"/> NO
2.	Are the Main-I & Main-II relays connected to two separate DC sources (Group-A and Group-B)	<input type="checkbox"/> YES <input type="checkbox"/> NO
3.	Is the Distance protection (Non-switched type, suitable for 1-ph & 3-ph tripping) as Main1 and Main2 provided to ensure selectivity & reliability for all faults in the shortest possible time	<input type="checkbox"/> YES <input type="checkbox"/> NO
4.	Is both main-I & Main-II distance relay are numerical design having Quadrilateral or Polygon operating characteristic	<input type="checkbox"/> YES <input type="checkbox"/> NO
5.	In the Main-I / Main-II Distance protection, Zone-I is set cover 80% of the protected line section	<input type="checkbox"/> YES <input type="checkbox"/> NO
6.	In the Main-I / Main-II distance protection, Zone-2 is set cover 120% of the protected line section in case of Single circuit line and 150% in case of Double circuit line	<input type="checkbox"/> YES <input type="checkbox"/> NO
7.	In the Main-I / Main-II distance protection, Zone-3 is set cover 120% of the total of protected line section plus longest line at remote end as a minimum.	<input type="checkbox"/> YES <input type="checkbox"/> NO
8.	Resistive reach for Ground fault element set to give maximum coverage considering fault resistance, arc resistance & tower footing resistance. ( In case, It is not possible to set the ground fault and phase fault reaches separately, load point encroachment condition imposed on Phase fault resistive reach shall be applied)	<input type="checkbox"/> YES <input type="checkbox"/> NO
9.	Resistive reach for Phase fault element set to give maximum coverage subject to check of possibility against load point encroachment considering minimum expected voltage and maximum load.	<input type="checkbox"/> YES <input type="checkbox"/> NO
10.	In case of short lines, is manufacturers recommendation considered in respect of resistive setting vis a vis reactance setting to avoid overreach.	<input type="checkbox"/> YES <input type="checkbox"/> NO
11.	Is Zone-2 time delay of Main-I / Main-II distance relay set to 0.350 seconds ? In case any other value has been set for Zone-II timer, kindly specify the value and justification thereof.	<input type="checkbox"/> YES <input type="checkbox"/> NO
12.	Is Zone-3 timer is set to provide discrimination with the operating time of relays at adjacent sections with which Zone-3 reach of relay is set to overlap. Please specify the Zone-3 time set.	<input type="checkbox"/> YES <input type="checkbox"/> NO
13.	Is Zone-4 reach set in reverse direction to cover expected levels of apparent bus bar fault resistance, when allowing for multiple in feeds from other circuits?	<input type="checkbox"/> YES <input type="checkbox"/> NO
14.	Is reverse looking Zone-4 time delay set as Zone-2 time delay?	<input type="checkbox"/> YES <input type="checkbox"/> NO



15.	Is Switch on to fault (SOTF) function provided in distance relay to take care of line energisation on fault?  Whether SOTF initiation has been implemented using hardwire logic In case of Breaker and half switching scheme, whether initiation of line SOTF from CB closing has been interlocked with the other CB	<input type="checkbox"/> YES <input type="checkbox"/> NO  <input type="checkbox"/> YES <input type="checkbox"/> NO  <input type="checkbox"/> YES <input type="checkbox"/> NO
16.	Whether VT fuse fail detection function has been correctly set to block the distance function operation on VT fuse failure	<input type="checkbox"/> YES <input type="checkbox"/> NO
17.	Is the sensitive IDMT directional E/F relay (either separate relay or built-in function of Main relay) for protection against high resistive earth faults?	<input type="checkbox"/> YES <input type="checkbox"/> NO
18.	Is additional element (Back-up distance) for remote back-up protection function provided in case of unit protection is used as Main relay for lines?	<input type="checkbox"/> YES <input type="checkbox"/> NO
19.	In case of Cables, is unit protection provided as Main-I & Main-II protection with distance as back-up.	<input type="checkbox"/> YES <input type="checkbox"/> NO
20.	Are the line parameters used for setting the relay verified by field testing	<input type="checkbox"/> YES <input type="checkbox"/> NO
21.	Is Two stages Over-Voltage protection provided for 765 & 400kV Lines? Do you apply grading in over-voltage setting for lines at one station. Please specify the setting values adopted for: Stage-I : (typical value - 106 to 112 % , delay : 4-7 Sec) Stage-II: (typical value - 140 to 150%, delay: 0 to 100msec.)	<input type="checkbox"/> YES <input type="checkbox"/> NO  <input type="checkbox"/> YES <input type="checkbox"/> NO  .....
22.	Is 1-ph Auto –reclosing provided on 765, 400 & 220kV lines? Please specify the set value: Dead time: (typical 1 Sec) Reclaim time: (typical 25 Sec)	<input type="checkbox"/> YES <input type="checkbox"/> NO  ..... .....
23.	Is the Distance communication. Scheme Permissive Over Reach (POR) applied for short lines and Permissive Under Reach (PUR) applied for long lines? If any other communication scheme has been applied, please provide the detail with justification thereof.	<input type="checkbox"/> YES <input type="checkbox"/> NO  .....
24.	Is the Current reversal guard logic for POR scheme provided on Double circuit lines?	<input type="checkbox"/> YES <input type="checkbox"/> NO
25.	In case the protected line is getting terminated at a station having very low fault level i.e. HVDC terminal, whether weak end-infeed feature has been enabled in respective distance relay or not	<input type="checkbox"/> YES <input type="checkbox"/> NO
26.	In case of protected line is originating from nuclear power station, are the special requirement (stability of nuclear plant auxiliaries) as required by them has been met	<input type="checkbox"/> YES <input type="checkbox"/> NO
27.	What line current , Voltage and Load angle have been considered for Load encroachment blinder setting and what is the resultant MVA that the line can carry without load encroachment. (In the absence of Load encroachment blinder function, this limit shall be applied to Zone-3 phase fault resistive reach.)	I= V= Angle: S=
28.	a) What are the Zones blocked on Power swing block function: b) Setting for Unblock timer: (typical 02 second)  c) Out of Step trip enabled	Z1 / Z2 / Z3 / Z4  Time:  <input type="checkbox"/> YES <input type="checkbox"/> NO
29.	Whether the location of Out of step relay has been identified on the basis of power system simulation studies	<input type="checkbox"/> YES <input type="checkbox"/> NO

<b>30.</b>	a) Is Disturbance recorder and Fault locator provided on all line feeder ?	<input type="checkbox"/> YES <input type="checkbox"/> NO
	b) Whether standalone or built in Main relay	Standalone / built-in
	c) Whether DR is having automatic fault record download facility to a central PC	<input type="checkbox"/> YES <input type="checkbox"/> NO
	d) Whether DR is time synchronised with the GPS based time synchronising equipment	<input type="checkbox"/> YES <input type="checkbox"/> NO
	e) Whether DR analog channels contain line phase & neutral current and line phase & neutral voltage.	<input type="checkbox"/> YES <input type="checkbox"/> NO
	f) Whether DR digital channel as a minimum contain the CB status, Main-I & II trip status, LBB trip status, Over-voltage trip status, Stub protn trip status, Permissive and direct carrier receive status, Line reactor trip status.	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>31.</b>	Does the Setting document for the numerical relays (IED) contain all the settings for all functions that are used and indicates clearly the functions not used (to be Blocked / Disabled). Are all default settings validated or revised settings given in the setting document?	<input type="checkbox"/> YES <input type="checkbox"/> NO

## B. Power Transformers

<b>1.</b>	Do you use Group A and Group B protections connected to separate DC sources for power transformers	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>2.</b>	Do you follow CBIP guideline (274 & 296) for protection setting of transformer	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>3.</b>	Do you use duplicated PRD and Bucholtz initiating contact for power transformers at 765kV and 400kV levels	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>4.</b>	Do you classify transformer protections as below in groups: Group A • Biased differential relay • PRD , WTI • Back up Protection(HV) • Over fluxing protection(HV) Group B Restricted earth fault (REF) relay Buchholz Protection, OTI Back up Protection(MV) Over fluxing protection(MV)	<input type="checkbox"/> YES <input type="checkbox"/> NO Group A or B
<b>5.</b>	In case of Breaker & half switching scheme, whether CT associated with Main & Tie Breakers are connected to separate bias winding of the low impedance Biased differential protection in order to avoid false operation due to dissimilar CT response.	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>6.</b>	Is Restricted earth fault (REF) protection used a high impedance type	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>7.</b>	Are Main protection relays provided for transformers are of numerical design.	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>8.</b>	a) Are directional over current & earth fault relays provided as back-up protection of Transformer are of numerical design.	<input type="checkbox"/> YES <input type="checkbox"/> NO
	b) Do the back-up earth fault relays have harmonic restrain feature	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>9.</b>	Is Fire protection system (HVW type) provided for power transformer and functioning	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>10.</b>	a) Is the Disturbance recorder provided for Transformer feeder	<input type="checkbox"/> YES <input type="checkbox"/> NO
	b) Whether standalone or built in Main relay	Standalone/built-in
	c) Whether DR is having automatic fault record download facility to a central PC	<input type="checkbox"/> YES <input type="checkbox"/> NO
	d) Whether DR is time synchronised with the GPS time synchronising equipment	<input type="checkbox"/> YES <input type="checkbox"/> NO

<b>11.</b>	Does the Setting document for the numerical relays (IED) contain all the settings for all functions that are used and indicates clearly the functions not used (to be Blocked / Disabled). Are all default settings validated or revised settings given in the setting document?	<input type="checkbox"/> YES <input type="checkbox"/> NO
------------	--	--

## C. Shunt Reactors

<b>1.</b>	Do you use Group A and Group B protections connected to separate DC sources for reactors	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>2.</b>	Do you follow CBIP guideline (274 and 296) for protection setting of reactors	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>3.</b>	Do you use duplicated PRD and Bucholtz initiating contact for Reactors at 765kV and 400kV levels	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>4.</b>	Do you classify Reactor protections as below in groups: <div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <b>Group A</b>            • Biased differential relay            • PRD , WTI            • Back up impedance protection         </div> <div style="width: 45%;"> <b>Group B</b>            R.E.F Protection            Buchholz Protection, OTI            Direction O/C &amp; E/F relay         </div> </div>	<input type="checkbox"/> YES <input type="checkbox"/> NO  Group    A or B
<b>5</b>	In case of Breaker & half switching scheme, whether CT associated with Main & Tie Breakers are connected to separate bias winding of the low impedance Biased differential protection in order to avoid false operation due to dissimilar CT response.	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>6</b>	Is Restricted earth fault (REF) protection used a high impedance type	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>7</b>	Are Main & back-up protection relays provided for Reactor are of numerical design.	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>8</b>	Is Fire protection system (HVW type) provided for Reactor and functioning	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>9</b>	a) Is the Disturbance recorder and Fault locator provided on all the Shunt Reactors used in 765 kV, 400 kV substations? b) Whether standalone or built in Main relay c) Whether DR is having automatic fault record download facility to a central PC	<input type="checkbox"/> YES <input type="checkbox"/> NO  Standalone/built-in <input type="checkbox"/> YES <input type="checkbox"/> NO
<b>10.</b>	Does the Setting document for the numerical relays (IED) contain all the settings for all functions that are used and indicates clearly the functions not used (to be Blocked / Disabled). Are all default settings validated or revised settings given in the setting document?	<input type="checkbox"/> YES <input type="checkbox"/> NO

## D. Bus bars

<b>1.</b>	Bus Bar protection for 765, 400 & 220kV buses is provided	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>2.</b>	Duplicated Bus bar protection is provided for 765kV and 400kV buses	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>3.</b>	CBIP guideline for Protection (274 and 296) settings is followed	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>4</b>	In an existing substation if CTs are of different ratios, is biased type bus protection provided.	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>5</b>	In stations where single bus bar protection is provided, is backup provided by reverse looking elements of distance relays or by second zone elements of remote end distance relays?	<input type="checkbox"/> YES <input type="checkbox"/> NO

<b>6</b>	In case of GIS where burn through time of SF6 is shorter than remote back up protection is the bus bar protection duplicated irrespective of voltage level?	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>7</b>	Since it is difficult to get shutdowns to allow periodic testing of bus protection, numerical bus protections with self-supervision feature is an answer. Is this followed?	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>8</b>	Does the Setting document for the numerical relays (IED) contain all the settings for all functions that are used and indicates clearly the functions not used (to be Blocked / Disabled). Are all default settings validated or revised settings given in the setting document?	<input type="checkbox"/> YES <input type="checkbox"/> NO

## E. Disturbance Recorder (DR) and Event Logger (EL)

<b>1</b>	a) Is the Disturbance recorder and Fault locator provided on all line feeders of 765, 400 & 220kV substations? b) Whether standalone or built in Main relay c) Whether DR is having automatic fault record download facility to a central PC d) Whether Central PC for DR , EL are powered by Inverter (fed from station DC)	<input type="checkbox"/> YES <input type="checkbox"/> NO Standalone / built-in <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO
<b>2.</b>	Whether DR is having the following main signals for lines: <u>Analogue signals:</u> <ul style="list-style-type: none"> <li>From CT: IA, IB, IC, IN</li> <li>From VT: VAN, VBN, VCN</li> <li>From Aux. VT: V0</li> </ul> <u>Digital Signals</u> <ul style="list-style-type: none"> <li>Main 1 Carrier receive</li> <li>Main 1 Trip</li> <li>Line O/V Stage I / Stage II</li> <li>Reactor Fault Trip</li> <li>Stub Protection Operated.</li> <li>Main II Trip</li> <li>Main II Carrier Receive</li> <li>Direct Trip CH I / II</li> <li>CB I Status (PH-R, Y &amp; B)</li> <li>CB II Status (PH R, Y &amp; B)</li> <li>Bus bar trip</li> <li>Main / Tie CB LBB Operated</li> <li>Main / Tie Auto-reclose operated.</li> </ul> DR for Transformer / Reactor feeder should contain analog channel like input currents & voltage. Binary signal include all protection trip input, Main & Tie CB status, LBB trip	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>3.</b>	Whether substation (765, 400 , 220kV) is having Event logger facility (standalone or built-in-SAS)	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>4.</b>	Whether GPS based time synchronizing equipment is provided at the substation for time synchronizing of Main relays / DR/ Event logger / SAS/ PMU / Line Current Differential Relays	<input type="checkbox"/> YES <input type="checkbox"/> NO

## F. Circuit Breakers

<b>1.</b>	Is breaker fail protection ( LBB / BFR) provided for all the Circuit Breakers at 220kV , 400kV & 765kV rating	<input type="checkbox"/> YES <input type="checkbox"/> NO
<b>3.</b>	For Circuit Breaker connected to line feeder / transformer feeder, whether operation of LBB / BFR sends direct trip signal to trip remote end breaker ?	<input type="checkbox"/> YES <input type="checkbox"/> NO

4.	For lines employing single phase auto reclosing, Is start signal from protection trip to LBB / BFR relay is given on single phase basis?	<input type="checkbox"/> YES <input type="checkbox"/> NO
5.	Is separate relay provided for each breaker and the relay has to be connected from the secondary circuit of the CTs associated with that particular breaker?	<input type="checkbox"/> YES <input type="checkbox"/> NO
6.	Is LBB relay provided with separate DC circuit independent from Group-A and Group-B Protections?	<input type="checkbox"/> YES <input type="checkbox"/> NO
7.	Is the LBB initiation provided with initiating contact independent of CB trip relay contact?	<input type="checkbox"/> YES <input type="checkbox"/> NO
8.	Is Separation maintained between protective relay and CB trip coil DC circuit so that short circuit or blown fuse in the CB circuit will not prevent the protective relay from energizing the LBB scheme?	<input type="checkbox"/> YES <input type="checkbox"/> NO
9.	Is LBB relay initiated by Bus bar protection in addition to other fault sensing relays, since failure of CB to clear a bus fault would result in the loss of entire station if BFP relay is not initiated?	<input type="checkbox"/> YES <input type="checkbox"/> NO
10.	Is tripping logic of the bus bar protection scheme used for LBB protection also?	<input type="checkbox"/> YES <input type="checkbox"/> NO
11.	Are the special considerations provided to ensure proper scheme operation by using Circuit Breaker contact logic in addition to current detectors in cases breaker-fail relaying for low energy faults like buckholz operation?	<input type="checkbox"/> YES <input type="checkbox"/> NO
12.	Are the Current level detectors set as sensitive as the main protection? (Generally setting of 0.2 A is commonly practiced for lines and transformers)	<input type="checkbox"/> YES <input type="checkbox"/> NO
13.	Is timer set considering breaker interrupting time, current detector reset time and a margin? (Generally a timer setting of 200ms has been found to be adequate)	<input type="checkbox"/> YES <input type="checkbox"/> NO
14.	Is the back-up fault clearance time is shorter than the operating time of the remote protections (distance relay Zone-2) ?	<input type="checkbox"/> YES <input type="checkbox"/> NO
15.	Is the breaker failure protection provided with two steps (First stage – retrip own CB, Second stage- Trip all associated CBs) . This mitigates unwanted operation of breaker failure protection during maintenance and fault tracing.	<input type="checkbox"/> YES <input type="checkbox"/> NO
16.	Is the breaker failure protection hardware provided is separate from line /transformer feeder protection?	<input type="checkbox"/> YES <input type="checkbox"/> NO

## G. Communication systems

1.	a) Do you use PLCC for tele-protection of distance relays at 765, 400 & 220kV feeders b) Specify type of coupling c) Whether redundant PLCC channels provided for 400 & 765kV lines d) Specify number of PLCC channels per circuit : e) Whether dependability & security of each tele-protection channel measured & record kept ?	<input type="checkbox"/> YES <input type="checkbox"/> NO (Ph-Ph / Ph-G/ Inter-ckt) <input type="checkbox"/> YES <input type="checkbox"/> NO ( One / two) <input type="checkbox"/> YES <input type="checkbox"/> NO
----	---	---

2.	a) In case you use OPGW for tele-protection, are they on geographically diversified route for Main-I and Main-II relay? b) Whether dedicated fibre is being used for Main-I / Main-II relay or multiplexed channel are being used.	<input type="checkbox"/> YES <input type="checkbox"/> NO  Dedicated / multiplexed
----	---	---

## H. Station DC supply systems

1.	Do you have two separate independent DC system (220V or 110V) (Source-A and Source-B)	<input type="checkbox"/> YES <input type="checkbox"/> NO
2.	Do you have two independent DC system (48V) for PLCC (source-A and source-B)	<input type="checkbox"/> YES <input type="checkbox"/> NO
3.	There is no mixing of supplies from DC source-A and DC source-B	<input type="checkbox"/> YES <input type="checkbox"/> NO
4.	Whether the protection relays and trip circuits are segregated into two independent system fed through fuses from two different DC source	<input type="checkbox"/> YES <input type="checkbox"/> NO
5.	Whether Bay wise distribution of DC supply done in the following way: a) Protection b) CB functions c) Isolator / earth switch functions d) Annunciation / Indications e) Monitoring functions	<input type="checkbox"/> YES <input type="checkbox"/> NO
6	Whether following has been ensured in the cabling: a) Separate cables are used for AC & DC circuits b) Separate cables are used for DC-I & DC-II circuits c) Separate cables are used for different cores of CT and CVT outputs to enhance reliability & security	<input type="checkbox"/> YES <input type="checkbox"/> NO
7	Is guidelines prescribed in CBIP manual 274 & 296 followed in general	<input type="checkbox"/> YES <input type="checkbox"/> NO

## I. PERFORMANCE INDICES

1.	Is there a system of periodically measuring Dependability & Security of Protection system (as given in CBIP manual 296) and recorded	<input type="checkbox"/> YES <input type="checkbox"/> NO
2.	Is there a system of periodically measuring Dependability of switchgear associated with Protection system and recorded	<input type="checkbox"/> YES <input type="checkbox"/> NO
3.	Is there a process of Root cause analysis of unwanted tripping events	<input type="checkbox"/> YES <input type="checkbox"/> NO
4.	Are improvement action like revision of relay setting, better maintenance practices, modernising & retrofitting of switching & protection system taken based on above data.	<input type="checkbox"/> YES <input type="checkbox"/> NO
5.	Is attention also given to DC supply system, tele-protection signalling, healthiness of tripping cables, terminations etc. in order to improve the performance of fault clearance system	<input type="checkbox"/> YES <input type="checkbox"/> NO

## J. ADDITIONAL CHECKS FOR SERIES COMPENSATED LINES

1.	What is the operating principle of Main protection employed	<input type="checkbox"/> Distance <input type="checkbox"/> Line Current diff.
----	---	--

2.	Are both main-I & Main-II distance relay are numerical design	<input type="checkbox"/> YES <input type="checkbox"/> NO
3.	Are both main-I & Main-II distance relay suitable for Series compensated lines	<input type="checkbox"/> YES <input type="checkbox"/> NO
4.	Are POR tele-protection scheme employed for distance relays	<input type="checkbox"/> YES <input type="checkbox"/> NO
5.	Position of Line VT provided on series compensated line	<input type="checkbox"/> Between Capacitor and line <input type="checkbox"/> Between Capacitor and Bus
6.	What is the under reaching (Zone 1) setting used in teleprotection schemes (Local & Remote end)	% of line length Rationale:
7.	What is the overreaching (Zone 2) setting in used teleprotection schemes	% of line length Rationale:
8.	What kinds of measurement techniques are used to cope with voltage inversion?	<input type="checkbox"/> Phase locked voltage memory <input type="checkbox"/> Intentional time delay Other, specify:
9.	Whether system studies carried out to check the possibility of current inversion due to series compensation	<input type="checkbox"/> YES <input type="checkbox"/> NO
10.	Whether any system studies conducted to find the impact of series compensation on the performance of protections installed on adjacent lines? If yes, how many lines were found to be affected. Pl. specify _____	<input type="checkbox"/> YES <input type="checkbox"/> NO
11.	If YES, are the affected protections on adjacent lines changed / setting revised after the introduction of series compensation?	<input type="checkbox"/> YES <input type="checkbox"/> NO
12.	Is dynamic simulation done to fine tune settings of distance relay installed on series compensated double circuit lines?	<input type="checkbox"/> YES <input type="checkbox"/> NO
13.	Whether performance of directional earth fault relay verifies by simulation studies	<input type="checkbox"/> YES <input type="checkbox"/> NO
14.	When is flashover of spark gaps expected?	<input type="checkbox"/> For protected line Faults up to _____ ohms <input type="checkbox"/> For external faults an adjacent lines
15.	Whether measures taken for under/overreach problems at sub-harmonic oscillations?	<input type="checkbox"/> YES <input type="checkbox"/> NO
16.	Whether MOV influence considered while setting the distance relay reach	<input type="checkbox"/> YES <input type="checkbox"/> NO
17.	Have you experienced any security problems (Relay mal-operation) with high frequency transients caused by <input type="checkbox"/> Flashover of spark gaps <input type="checkbox"/> Line energisation Other, specify:	<input type="checkbox"/> YES <input type="checkbox"/> NO
18.	If YES, how the above problem has been addressed?	



### List of important transmission lines in ER which tripped in November-2021

Sl. No.	LINE NAME	TRIP DATE	TRIP TIME	RESTORATION DATE	RESTORATION TIME	Relay Indication on LOCAL END	Relay Indication on REMOTE END	Reason	Fault Clearance time in msec	Remarks	LOCAL END UTILITY	REMOTE END UTILITY	Utility Response
1	400 KV FSTPP-DURGAPUR-2	04-11-2021	09:44	04-11-2021	12:55	FSTPP: B_N, Zone-1, 104 km, 3.5 kA	Durgapur: B_N, Zone-1, 56.94 km, 4.59 kA	B-Earth	200	Main bay LBB operated at Farakka. 400 kV Bus-1 tripped. Three phase autoreclosure occurred at Durgapur after 1 second. O/V st-2 appeared at Durgapur during A/r. Reason maybe sahred	NTPC FSTPP	PG ER-2	Issue with A/r scheme at Durgapur end. Rectified.
2	220 KV NEW PURNEA-MADHEPUR A-1	06-11-2021	10:58	06-11-2021	11:16	New Purnea: R_N, 78.54 km, 2.49 kA		R-Earth	350	Carrier received at New Purnea but tripped in Zone-2 time. A/r successful from Madhepura only	PG ER-1	BSPT CL	Siemens relay at New Purnea is not receiving carrier signal. Response from OEM awaited.
3	400 KV PPSP-BIDHANNA GAR-2	06-11-2021	12:03	06-11-2021	12:25	PPSP: R_N, Zone-1, 144.2 km	Bidhannagar: R_N, Zone-1, 36.4 km, 6.1 kA	R-Earth	100	Three phase tripping at Bidhannagar	WBSE TCL	WBSE TCL	A/r kept out of service as per OEM advice.



4	400 KV PPSP- BIDHANNA GAR-1	06-11-2021	14:21	06-11-2021	14:42	PPSP: R_N, Zone-1, 105.1 km	Bidhannagar: R_N, Zone-1, 85.65 km, 6.9 kA	R-Earth	100	Three phase tripping at Bidhannagar	WBSE TCL	WBSE TCL	A/r kept out of service as per OEM advice.
5	220 KV CHANDAUT I- SONENAGA R-1	07-11-2021	23:20	08-11-2021	00:23	Chandauti: R_N, 50.8 km, 3.2 kA	Sonenagar: R_N, 20.17 km, 2.195 kA	R-Earth	250	A/r successful from Chandauti only. No A/r attempt at Sonenagar	PMTL	BSPT CL	Problem in selector switch. A/r scheme also not functioning properly
6	400 KV MERAMUN DALI- LAPANGA-2	08-11-2021	12:54	08-11-2021	13:03	Tripped while checking VT fuse	Didn't trip	No fault	NA	No fault in line however, distance relay operated at Meramundali	OPTCL	OPTCL	fused, while rectifying that, wires of other two healthy phase got opened and tripping command initiated. On time synch issue of DR
7	400 KV BARH- PATNA-1	08-11-2021	13:57	08-11-2021	14:49		Didn't trip	No fault	NA	Reason maybe shared by Barh	NTPC Barh	PG ER- 1	DT initiated locally at Barh end. Issue in channel-1, referred to OEM.
8	400 KV RANGPO- DIKCHU-1	08-11-2021	22:24	08-11-2021	22:43	DT received	Didn't trip	No fault	NA	DT received at Rangpo. Reason maybe shared by Dikchu	PG ER- 2	Dikchu	Isolator, earth switch status in SAS got in error state. BCU was restarted which sent DT to remote end. Dikchu was advised to intimate ERLDC if such activity is being carried out at Dikchu
9	220 KV CHANDAUT I- SONENAGA R-2	11-11-2021	14:15	11-11-2021	15:02	Chandauti: R_N, Zone-1, 52.6 km, 3.41 kA	Sonenagar: R_N, Zone-1, 21.6 km, 2.1 kA	R-Earth	100	A/r successful from Chandauti only. No A/r attempt at Sonenagar, other two phase tripped after 1 second	PMTL	BSPT CL	Problem in selector switch. A/r scheme also not functioning properly
10	400 KV PATNA- BARH-1	13-11-2021	04:09	13-11-2021	04:45	Didn't trip	DT received	No fault	NA	Reason maybe shared by Barh	PG ER- 1	NR	DT initiated locally at Barh end. Issue in channel-1, referred to OEM.

11	400 KV PATNA- BARH-1	13-11-2021	08:36	13-11-2021	09:58	Didn't trip	DT received	No fault	NA	Reason maybe shared by Barh	PG ER- 1	NTPC Barh	DT initiated locally at Barh end. Issue in channel-1, referred to
12	400 KV JEERAT- BAKRESWA R-1	17-11-2021	16:20	17-11-2021	17:49	Didn't trip	Pole discrepancy at Bakreswar end			Y_ph CB at Bakreswar tripped without any fault. 1.5 seconds later other two phase tripped on PD	WBSE TCL	WBSE TCL	No issue found, however PD timer replaced at Bakreswar as a precautionary measure
13	400 KV PPSP- BIDHANNA GAR-2	21-11-2021	12:39	21-11-2021	12:50	PPSP: R_N, 141.5 km, Zone-1	Bidhannagar: R_N, Zone-1, 47.09 km, 6.275 kA	R-Earth	100	Three phase tripping at Bidhannagar. A/r not in service	WBSE TCL	WBSE TCL	A/r kept out of service as per OEM advice.

**Creation and maintaining a Web based Protection  
Database and Desktop based Protection setting calculation  
tool for Eastern Regional Grid  
-Update and support activities  
01/11/2020 – 31/10/2021**

# SCOPE OF WORK

## Activities

**New S/S Data Collection**

**New Element Addition as per OCC meetings**

**Data updation in PSCT & PDMS**

**Training on Protection study & PDMS**

**Software Enhancement**

**Server Maintenance**

**DMNS Reporting**

**Technical Analysis for Tripping Incidents**

# Technical Services

- ❖ Sikkim OC and EF coordination was done.
- ❖ Tripping analysis at Bodhgaya .
- ❖ Patna PG Islanding Study.
- ❖ Power Map update for all states in a regular span.
- ❖ Attended all PCC meetings for protection consultancy.

# OCC track update

Sl.No	DETAILS OF ELEMENTS
1	132/33 KV, 31.5 MVA Transformer 3 Kakdwip 132 KV S/S (WBSETCL)
2	132 KV Durgapur-Panagarh GISS Ckt 1 & 2
3	132 kV Marsaghai – Kendrapara RTSS ckt -II
4	160 MVA, 220/132 kV Auto Transformer - II charged at Grid S/S, Kesinga
5	220 kV Bus -I & Bus -II charged at Grid S/S, Kesinga
6	132 kV Bhalumaska RTSS feeder bay charged at Grid S/S Therubali
7	132KVMokamah (BGCL) – Hathidah (BSPTCL) D/C
8	220kv GIS Mokama-Begusarai D/C
9	220kV GIS Mokama-Biharsharif D/C
10	400kV Sagardighi – Gokarna-I
11	400kV Sagardighi – Gokarna- II
12	Anti-theft charge of 765kV New RanchiMedinipur Ckt 2 with LR
13	Anti-theft charge of 765kV New RanchiMedinipur Ckt 1 with LR
14	400kV Muzaffarpur-Dhalkebar-I
15	400kV Muzaffarpur-Dhalkebar-II
16	400/220 kV 315 MVA ICT 4 at Rourkela
17	400 kV Gaya-Chandauti Ckt II
18	400 kV Chandauti-NPGC Ckt II
19	400 kV Gaya-Chandauti Ckt I
20	400 kV Chandauti-NPGC Ckt I

# OCC track update

21	220 kV Arrah - Dumraon New Ckt I
22	220 kV Arrah - Dumraon New Ckt II
23	220 kV Nadokhar - Dumraon New Ckt I
24	220 kV Nadokhar - Dumraon New Ckt II
26	400 kV New Duburi TSL-1
27	765 kV Bus Reactor Bank-1 (3 x 110 MVAR)
28	765 kV New Ranchi-Medinipur T/L 1 along with switchable line reactor(3 x 80 MVAR and Spare 1 x 80 MVAR)
29	765 kV New Ranchi-Medinipur T/L 2 along with switchable line reactor(3 x 80 MVAR and Spare 1 x 80 MVAR)
30	220 kV Subhasgram-Baruipur D/C
31	Main bays of 400 kV Subhasgram-NEW Jeerat D/C at Subhagram
32	400 kV Main Bay of Binaguri-Bongaigaon 2 at Binaguri SS
33	400 kV Medinipur-Chanditala TL-I
34	400 kV Medinipur-Chanditala TL-II
35	400 kV Medinipur-Kharagpur TL-I
36	400 kV Medinipur-Kharagpur TL-II
37	400 kV Main Bus 1 at Medinipur
38	400 kV Main Bus 2 at Medinipur
39	765/400/33 kV 1500 MVA ICT-2 at Medinipur SS
40	765/400/33 kV 1500 MVA ICT-1 at Medinipur SS



# OCC track update

41	400 kV Bus reactor 2 at Medinipur SS
42	400 kV Bus reactor 1 at Medinipur SS
43	765 kV Main Bay at NEW Jeerat-1 and Tie Bay at Medinipur SS
44	765 kV Main Bay at NEW Jeerat-2 and Tie Bay at Medinipur SS
45	765 kV Bus Reactor Bank-2 (3 x 110 MVAR) at Medinipur SS
46	765 kV Ranchi-Medinipur TL-2 with switable line reactor(3x80 MVAR)
47	400 kV/220 kV 315 MVA ICT 2 at DSTPS(Andal)
48	400 kV/220 kV 500 MVA ICT 1 at Chandauti
49	220 kV bus coupler at Chandauti
50	400 kV/220 kV 500 MVA ICT 3 at Chandauti
51	400 kV/220 kV 500 MVA ICT 2 at Chandauti
52	220 kV may bay for 500 MVA ICT 1 at Chandauti
53	220 kV may bay for 500 MVA ICT 2 at Chandauti
54	220 Kv Main bay at Tashiding 1 at New Melli
55	220 Kv Main bay at Tashiding 2 at New Melli
56	400 kV/220 kV 315 MVA ICT 3 at Rourkela
57	400KV MAIN BAY OF SAGARDIGHI-2 AT JEERAT
58	400KV MAIN BAY OF NEW JEERAT-2 AT JEERAT
59	400KV MAIN BAY OF NEW JEERAT-1 AT JEERAT
60	400KV MAIN BAY OF SUBHASGRAM-1 AT JEERAT



# OCC track update

61	125MVAR 400KV B/R-2 AT CHANDAUTI
62	125MVAR 400KV B/R-1 AT CHANDAUTI
63	220KV/132KV 200 MVA ICT 3 AT CHANDAUTI
64	220KV/132KV 200 MVA ICT 1 AT CHANDAUTI
65	400KV MAIN BAY OF GAYA-1 AT CHANDAUTI
66	220KV MAIN BAY OF SONENAGAR-2 AT CHANDAUTI
67	220KV MAIN BAY OF SONENAGAR-1 AT CHANDAUTI
68	220KV MAIN BAY OF GAYA -2 AT CHANDAUTI
69	132KV MAIN BAY OF CHANDAUTI(BSPTCL)-2 AT CHANDAUTI
70	132KV MAIN BAY OF CHANDAUTI-1(BSPTCL) AT CHANDAUTI
71	132KV MAIN BAY OF RAFIGANJ-1 AT CHANDAUTI
72	132KV MAIN BAY OF SONENAGAR-1 AT CHANDAUTI
73	132KV MAIN BAY OF 220/132KV200 MVA ICT 3 AT CHANDAUTI
74	132KV MAIN BAY OF 220KV/132KV 200 MVA ICT 2 AT CHANDAUTI
75	132KV MAIN BAY OF 220KV/132KV 200 MVA ICT 1 AT CHANDAUTI
76	220KV MAIN BAY OF SONENAGAR-1 AT CHANDAUTI
77	400 KV GORAKHPUR MOTIHARI 2
78	220KV-CHANDAUTI -SONENAGAR-2
79	400 kV PATNA KISHANGANJ D/CLINE
80	23.5/765 KV, 3x315 MVA, GT-2,DARLIPALLI (NTPC)

# OCC track update

81	400 KV RANGPO-BINAGURI D/C
82	400KV-ALIPURDUAR (PG) JIGMELLING-1
83	400KV-ALIPURDUAR (PG) JIGMELLING-2
84	220KV - GAYA CHANDAUTI 1
85	400 KV BARH MOTIHARI 1
86	400/22 KV 3*260 MVA GT 3 AT NPGC
87	220KV - GAYA CHANDAUTI 2
88	400KV/220KV 500 MVA ICT 3 AT MALDA
89	400 KV GORAKHPUR MOTIHARI 1
90	220KV BUS SECTIONALIZER BAY OF ( 220KV BUS 1A AND 220KVBUS 1B) AT RONGNICHU
91	400KV MAIN BAY OF B/R 1 AT SITAMARHI
92	125MVAR 400KV B/R-2 AT SITAMARHI
93	220KV/132KV 100 MVA ICT 4 AT RANGPO
94	400KV-SITAMARHI-MOTIHARI-2
95	400KV-SITAMARHI-DARBHANGA (DMTCL)-2
96	400KV TIE BAY OF ( 400KV-SITAMARHI--2 AND FUTURE) AT MOTIHARI
97	400KV MAIN BAY OF SITAMARHI -2 AT MOTIHARI
98	400KV MAIN BAY OF MOTIHARI-2 AT SITAMARHI
99	400KV MAIN BAY OF DARBHANGA (DMTCL)-2 AT SITAMARHI
100	400KV TIE BAY OF ( SITAMARHI--1 AND SITAMARHI--2) AT DARBHANGA (DMTCL)

# OCC track update

101	400KV MAIN BAY OF SITAMARHI -2 AT DARBHANGA (DMTCL)
102	400KV-SITAMARHI-MOTIHARI-1
103	400KV MAIN BAY OF SITAMARHI -1 AT MOTIHARI
104	400KV TIE BAY OF ( 125MVAR 400KV B/R-2 AND 400KV--MOTIHARI-1) AT SITAMARHI
105	400KV MAIN BAY OF MOTIHARI-1 AT SITAMARHI
106	220KV/11KV 10 MVA ST AT RONGNICHU
107	220KV MAIN BAY OF STATION TRANSFORMER (ST) AT RONGNICHU
108	125MVAR 400KV B/R-1 AT SITAMARHI
109	220KV MAIN BAY OF 11/220KV GT1 AT RONGNICHU
110	220KV MAIN BAY OF 11/220KV GT2 AT RONGNICHU
111	220KV-DARBHANGA(DMTCL)-LAUKAHI-2
112	400KV TIE BAY OF ( 400KV--DARBHANGA (DMTCL)-2 AND 400KV/220KV 500 MVA ICT 2) AT SITAMARHI
113	400KV MAIN BAY OF 400KV/220KV 500 MVA ICT 2 AT SITAMARHI
114	400KV TIE BAY OF ( MOTIHARI-2 AND 500 MVA ICT 1) AT SITAMARHI
115	400KV MAIN BAY OF 400KV/220KV 500 MVA ICT 1 AT SITAMARHI
116	400KV/220KV 500 MVA ICT 2 AT SITAMARHI
117	400KV/220KV 500 MVA ICT 1 AT SITAMARHI
118	220KV BUS COUPLER BAY AT SITAMARHI
119	220KV/132KV 200 MVA ICT 2 AT SITAMARHI
120	220KV MAIN BAY OF 220KV/132KV 200 MVA ICT 2 AT SITAMARHI

# OCC track update

121	220KV/132KV 200 MVA ICT 1 AT SITAMARHI
122	220KV MAIN BAY OF 220KV/132KV 200 MVA ICT 1 AT SITAMARHI
123	132KV MAIN BAY OF 220KV/132KV 200 MVA ICT 2 AT SITAMARHI
124	220KV MAIN BAY OF MOTIPUR-2 AT SITAMARHI
125	220KV MAIN BAY OF MOTIPUR-1 AT SITAMARHI
126	220KV MAIN BAY OF RAXAUL -2 AT SITAMARHI
127	220KV MAIN BAY OF RAXAUL -1 AT SITAMARHI
128	132KV MAIN BAY OF RUNNISAIDPUR-2 AT SITAMARHI
129	132KV MAIN BAY OF RUNNISAIDPUR-1 AT SITAMARHI
130	132KV MAIN BAY OF PUPRI-2 AT SITAMARHI
131	132KV MAIN BAY OF PUPRI-1 AT SITAMARHI
132	132KV MAIN BAY OF 220KV/132KV 200 MVA ICT 1 AT SITAMARHI
133	220KV-SITAMARHI-MOTIPUR-2
134	220KV-SITAMARHI-MOTIPUR-1
135	400KV/220KV 315 MVA ICT 3 AT JEYPORE
136	400KV MAIN BAY OF 315 MVA ICT 3 AT MOTIHARI (DMTCL)
137	400KV TIE BAY OF ( 400KV-SITAMARHI--1 AND 315 MVA ICT 3 ) AT MOTIHARI
138	765KV 262 MVAR BR 1 AT DARLIPALI (DSTPS) along with Bays
139	400KV/220KV 315 MVA ICT 1 AT DSTPS(ANDAL)
140	33KV/0.415KV 0.630 MVA ICT 1 AT ROURKELA
141	220KV MAIN BAY OF 400KV/220KV 315 MVA ICT 1 AT DSTPS(ANDAL)

# OCC track update

142	400KV-SITAMARHI-MOTIHARI-2 DMTCL
143	400KV-SITAMARHI-DARBHANGA (DMTCL)-2
144	400KV TIE BAY OF ( 400KV-SITAMARHI--2 AND FUTURE) AT MOTIHARI
145	400KV MAIN BAY OF SITAMARHI -2 AT MOTIHARI
146	400KV MAIN BAY OF MOTIHARI-2 AT SITAMARHI
147	400KV MAIN BAY OF DARBHANGA (DMTCL)-2 AT SITAMARHI
148	400KV TIE BAY OF ( SITAMARHI--1 AND SITAMARHI--2) AT DARBHANGA (DMTCL)
149	400KV MAIN BAY OF SITAMARHI -2 AT DARBHANGA (DMTCL)
150	400KV-SITAMARHI-MOTIHARI-1
151	400KV MAIN BAY OF SITAMARHI -1 AT MOTIHARI
152	400KV TIE BAY OF ( 125MVAR 400KV B/R-2 AND 400KV--MOTIHARI-1) AT SITAMARHI
153	400KV MAIN BAY OF MOTIHARI-1 AT SITAMARHI
154	125MVAR 400KV B/R-1 AT SITAMARHI
155	220KV-DARBHANGA(DMTCL)-LAUKAHI-2
156	400KV TIE BAY OF ( 400KV--DARBHANGA (DMTCL)-2 AND 400KV/220KV 500 MVA ICT 2) AT SITAMARHI
157	400KV MAIN BAY OF 400KV/220KV 500 MVA ICT 2 AT SITAMARHI
158	400KV TIE BAY OF ( MOTIHARI-2 AND 500 MVA ICT 1) AT SITAMARHI
159	400KV MAIN BAY OF 400KV/220KV 500 MVA ICT 1 AT SITAMARHI
160	400KV/220KV 500 MVA ICT 2 AT SITAMARHI



# OCC track update

161	400KV/220KV 500 MVA ICT 1 AT SITAMARHI
162	220KV BUS COUPLER BAY AT SITAMARHI
163	220KV/132KV 200 MVA ICT 2 AT SITAMARHI
164	220KV MAIN BAY OF 220KV/132KV 200 MVA ICT 2 AT SITAMARHI
165	220KV/132KV 200 MVA ICT 1 AT SITAMARHI
166	220KV MAIN BAY OF 220KV/132KV 200 MVA ICT 1 AT SITAMARHI
167	132KV MAIN BAY OF 220KV/132KV 200 MVA ICT 2 AT SITAMARHI
168	220KV MAIN BAY OF MOTIPUR-2 AT SITAMARHI
169	220KV MAIN BAY OF MOTIPUR-1 AT SITAMARHI
170	220KV MAIN BAY OF RAXAUL -2 AT SITAMARHI
171	220KV MAIN BAY OF RAXAUL -1 AT SITAMARHI
172	132KV MAIN BAY OF RUNNISAIDPUR-2 AT SITAMARHI
173	132KV MAIN BAY OF RUNNISAIDPUR-1 AT SITAMARHI
174	132KV MAIN BAY OF RUNNISAIDPUR-2 AT SITAMARHI
175	132KV MAIN BAY OF RUNNISAIDPUR-1 AT SITAMARHI
176	132KV MAIN BAY OF 220KV/132KV 200 MVA ICT 1 AT SITAMARHI
177	220KV-SITAMARHI-MOTIPUR-2
178	220KV-SITAMARHI-MOTIPUR-1
179	400KV/220KV 315 MVA ICT 3 AT JEYPORE
180	400KV MAIN BAY OF 315 MVA ICT 3 AT MOTIHARI (DMTCL)

# OCC track update

181	400KV TIE BAY OF ( 400KV-SITAMARHI--1 AND 315 MVA ICT 3 ) AT MOTIHARI
182	400KV/220KV 315 MVA ICT 1 AT DSTPS(ANDAL)
183	220KV MAIN BAY OF 400KV/220KV 315 MVA ICT 1 AT DSTPS(ANDAL)
184	220KV-SITAMARHI-MOTIPUR-1
185	765KV TIE BAY OF 262MVAR BUS REACTOR-1 AND GT-1 AT DARLIPALLI
186	400KV JEERAT-SAGARDIGHI 2
187	400KV JEERAT-SUBHASGRAM 2
188	132KV-SITAMARHI-RUNNISAIDPUR 2
189	132KV-SITAMARHI-RUNNISAIDPUR 1
190	400KV-BAHARAMPUR-BHERAMERA 3
191	220KV MAIN BAY OF JAYNAGAR-3AT JEYPORE
192	220KV MAIN BAY OF JAYNAGAR-4AT JEYPORE
193	400KV MAIN BAY OF 315 MVA ICT-III AT SUBHASGRAM(PG)
194	400KV MAIN BAY OF 315 MVA ICT-IV AT SUBHASGRAM(PG)
195	400KV ALIPURDUAR-JIGMELLING 1
196	400KV ALIPURDUAR-JIGMELLING 2
197	220KV JAYNAGAR-JEYPORE-3
198	220KV JAYNAGAR-JEYPORE-4
199	400KV- JEERAT-NEW JEERAT-1
200	400KV- JEERAT-NEW JEERAT-2

# OCC track update

201	400KV- JEERAT-NEW JEERAT-1
202	400KV- JEERAT-NEW JEERAT-2
203	400KV BAHARAMPUR-BHERAMARA 4
204	132KV NAGARUNTARI-SONENAGAR 1(LILO OF 132 KV RIHAND SONENAGAR CKT 1 NAGARUNTARI)
205	400KV DHANBAD-RANCHI1(LILO OF 400KV RANCHI-MAITHON RB D/C
206	400KV DHANBAD-MAITHON RB-1(LILO OF 400KV RANCHI-MAITHON RB D/C)
207	400KV DHANBAD-RANCHI2(LILO OF 400KV RANCHI-MAITHON RB D/C
208	400KV DHANBAD-MAITHON RB-2(LILO OF 400KV RANCHI-MAITHON RB D/C)
209	125KV BARIPADA-BANGIRPOSHI 2
210	220KV RANCHI-RMGARH- 1
211	220KV RANCHI-MTPS(DVC)- 1



# Training on PDMS & PSCT

## WEBINAR on PDMS and protection study (State Wise)

Sl no.	Date	State	Topic	Attended
1	12.04.2021	Bihar	PDMS	44
2	13.04.2021	Bihar	Protection Study	44
3	20.04.2021	West Bengal	PDMS	05
4	21.04.2021	West Bengal	Protection Study	05
5	27.09.2021	Jharkhand	PDMS	55
6	28.09.2021	Jharkhand	Protection Study	55
7	04.10.2021	Odisha	PDMS	58
8	05.10.2021	Odisha	Protection Study	58

# New S/S Data Collection

Collected SS LIST 2021				
Sl. No.	SS Name	Voltage Level	Utility	State
1	JAIPATNA	220/132/33 kV	OPTCL	ODISHA
2	SATASANKHA	132/33 kV	OPTCL	ODISHA
3	ASKA NEW	220/132/33 kV	OPTCL	ODISHA
4	BETNOTI	132/33 kV	OPTCL	ODISHA
5	KASHIPUR	220/33 kV	OPTCL	ODISHA
6	MANCHESWAR	132/33 kV	OPTCL	ODISHA
7	NARSINGHPUR	220/33 kV	OPTCL	ODISHA
8	UDALA	132/33 kV	OPTCL	ODISHA
9	IBTPS	21/400 kV	OPGC	ODISHA
10	SUNDARGARH	765/400 kV	PGCIL	ODISHA
11	CHANDAUTI NEW	400/220/132 kV	PMTL	BIHAR
12	MOKAMAH	220/132 kV	BGCL	BIHAR
13	SITAMARHI	400/220/132 kV	PMTL	BIHAR

# New S/S Data Collection

Collected SS LIST 2021				
Sl. No.	SS Name	Voltage Level	Utility	State
14	KHAGARIA NEW	220/132/33 kV	BSPTCL	BIHAR
15	DUMRAON NEW	220/132/33 kV	BGCL	BIHAR
16	PANAGARH	132/33 kV	WBSETCL	WEST BENGAL
17	MOHITNAGAR	132/33 kV	WBSETCL	WEST BENGAL
18	MEDINIPORE	765/400 kV	PMJTL	WEST BENGAL
19	DINAHATA	132/33 kV	WBSETCL	WEST BENGAL
20	SALLAKE STADIUM	132/33 kV	WBSETCL	WEST BENGAL
21	BAGMUNDI	132/33 kV	WBSETCL	WEST BENGAL

# Software Update

Multiple DR download facility on Tripping incident page

Bug fixed for forgot password option on login page

Working on New PDMS Dashboard

Updation of Organization list

New user addition

Version Updates for PSCT

Regular Power MAP updation of ER

# Server Maintenance

**Regular Health check up for Live Server**

**UPS backup activity checking**

**Regular Server Temp file/Cache clearing**

**Regular Database storage backup of PDMS**

**Internet Speed monitoring for Server**

# DMNS

**Number of Case Raised by Utilities - 7**



**Number of Case Closed by PRDC - 7**



**SLD updated for all cases**



**PDMS database updated for all cases**



**THANK YOU**

SI No.	Name of the incidence	PCC Recommendation	Latest status
<b>106<sup>th</sup> PCC Meeting</b>			
1.	Tripping of Bus-1 at 220 kV Ramchandrapur on 20/08/2021 at 20:24 Hrs.	<p>In 106<sup>th</sup> PCC Meeting, PCC advised JUSNL following:</p> <ul style="list-style-type: none"> <li>➤ To restore the busbar protection at 220 kV Ramchandrapur S/s within a month.</li> </ul>	<p>➤ In 108<sup>th</sup> PCC Meeting, Regarding Bus Bar Protection, JUSNL informed that the same could not be restored as the visit of OEM engineers get delayed. PCC advised to take up the issue with higher authority for early restoration of the busbar protection.</p> <p><i>JUSNL informed that they are in process to place fresh tender for implementation of PLCC as well as bus bar protection and it is expected that implementation of both would be completed by April 2022.</i></p>
2.	Repeated Tripping of 132 kV Sultanganj- Deogarh D/C	In 106 <sup>th</sup> PCC Meeting, PCC advised BSPTCL to resolve all clearance issues in the line and complete the insulator replacement work at the earliest.	<i>BSPTCL informed that all clearance issues in the line had been resolved and insulator replacement work had also been completed.</i>
3.	Total Power Failure at Dumka S/s on 15/05/2021 at 12:01 Hrs	<p>Regarding 220 kV Maithon-Dumka-1, JUSNL intimated that there was card issue in PLCC panel. The OEM (M/s ABB) had been communicated regarding the issue and the same would be resolved by September' 21.</p> <p>In 108<sup>th</sup> PCC Meeting, JUSNL informed that work order would be placed after receiving the cost estimate from OEM. They stated that the PLCC link would be restored by December 2021.</p>	<i>JUSNL informed that PLCC link would be replaced by March-2022.</i>
4.	Grid event at 132 kV Motihari (DMTCL) S/S on 21-04-2021 at 20:19 hrs	In 106 <sup>th</sup> PCC Meeting, PMTL informed that offers received from	<i>PMTL representative informed that they are in process of</i>



		<p>OEM i.e., M/s TBEA regarding restoration of the damaged GIS section is under examination.</p> <p>Regarding timeline to complete the work, PMTL informed that since all materials required for restoration work are to be imported from China, it would take 40-50 days for restoration after placing the supply order.</p> <p>In 108<sup>th</sup> PCC Meeting, PMTL representative informed that an internal committee of Powergrid had visited site on 12<sup>th</sup> Nov 2021. PCC advised to submit the restoration plan of the damaged bus extension module.</p>	<p><i>placing the work order with TBEA authorized partner i.e. M/S Path Electrical. The quotation has been received and work order would be placed by end of December 2021.</i></p>
<b>107<sup>th</sup> PCC Meeting</b>			
5.	Disturbance at 220 kV Hajipur S/S on 28.09.2021 at 17:18Hrs	In 107 <sup>th</sup> PCC Meeting, PCC advised BSPTCL to submit action taken report for this disturbance in coordination with BGCL.	<i>BSPTCL informed that they had not received any action plan from BGCL. PCC advised BSPTCL to coordinate with BGCL for getting the report regarding the disturbance. BSPTCL was further advised to communicate BGCL to attend next PCC Meeting.</i>
6.	Islanding Performance and Observations during recent Islanding incidents in CESC system.	In 108 <sup>th</sup> PCC Meeting, CESC informed that a preliminary meeting was held with ERLDC. Based on the feedback, islanding events are being analyzed and the report would be submitted after completion of the analysis.	<i>MOM of meeting held between ERLDC and CESC regarding Islanding Performance and Observations during recent Islanding incidents in CESC system is attached at <b>Annexure C.3.6.</b></i>
7.	Tripping of DALTONGANJ – GARWA D/C lines.	<p>In 108<sup>th</sup> PCC Meeting, JUSNL informed that patrolling was carried out and vegetation issues were found at location no. 89, 90, 91. The same would be cleared within two weeks.</p> <p>Regarding auto-recloser scheme at Garwah end, they updated that</p>	<i>JUSNL informed that vegetation issue had been resolved. They further informed that auto recloser scheme had been checked and issues were rectified at Garhwa end.</i>

		scheme is being reviewed by the CRITL wing.	
8.	Repeated Tripping of 220 kV Joda- Ramchandrapur	<p>In 108<sup>th</sup> PCC Meeting, JUSNL informed that line patrolling was carried out for however no vegetation or clearance issues were found in the line.</p> <p>Regarding PLCC, they updated that issue had been communicated to OEM but they were facing difficulty in getting the availability of service engineers at site.</p>	<i>JUSNL informed that they are in process of placing fresh tender for implementation of PLCC as well as bus bar protection and it is expected that implementation of both would be completed by April 2022.</i>
<b>108<sup>th</sup> PCC Meeting</b>			
9.	Total Power Failure at 220 kV Ronginchu HEP on 20.10.2021 at 12:42 Hrs	PCC advised Ronginichu HEP to review the overcurrent relay settings at their end. It was suggested to review the directional feature and definite time settings of the O/C relay.	
10.	Total Power Failure at 220/132 kV Chatra(JUSNL) S/s on 09.10.2021 at 12:44 Hrs	<p>PCC advised JUSNL to resolve the carrier related issue at Chatra end and to ensure healthiness of PLCC for 220 kV Daltonganj-Chatra line.</p> <p>PCC further advised JUSNL to implement weak in-feed protection at Chatra end for 220 kV Daltonganj-Chatra lines.</p>	<i>JUSNL informed that weak in-feed protection had been implemented at Chatra end for 220 kV Daltonganj-Chatra lines and the carrier related issues were also resolved for the line.</i>
11.	Tripping of 400/220 kV 500 MVA ICT-1 & 2 at Darbhanga (DMTCL) S/s on 25.09.2021	PCC advised DMTCL to revise the ICT earth fault setting at Darbhanga end in line with the guidelines at the earliest.	<p><i>DMTCL informed that they had revised the ICT earth fault setting at Darbhanga end in line with the guidelines recommended by PCC.</i></p> <p><i>ERLDC opined that line differential protection needs to be implemented in 220 kV Darbhanga-Darbhanga (DMTCL) D/c line. PCC advised BSPTCL to submit their plan for implementing line</i></p>

			<i>differential protection for the above line.</i>
--	--	--	--

**MOM Held at ERLDC on 30.11.2021 between Officials of ERLDC & CESC regarding  
Agenda Item No. B. 8 of 185<sup>th</sup> OCC Meeting on 23.11.2021**

**Members Present:**

<b>ERLDC</b>	<b>CESC</b>
Mr Gopal Mitra	Mr Snehasis Samaddar
Mr Rajib Sutradhar	Mr Sibir Roy
Mr Amaresh Mallick	Mr Arunava Sen Gupta
Mr Shyamal Konar	Mr Susovan Narayan Choudhury
Mr Saugato Mondal	Mr Arghya Ghosal
Mr Saurav Kr. Sahay	
Mr Chandan Kumar	
Mr Raj Protim Kundu	
Mr Alok Pratap Singh	
Mr Saibal Ghosh	

**UEL and PSS**

1. A holistic study will be carried out by CESC regarding PSS and UEL of BBGS - Will start from January, 2022 and will take 2-3 months.
2. Network for Synchronization of CESC System at 220 KV with Kasba S/S of WBSETCL is expected to be ready by March, 2022.
3. PSS and UEL performance of BBGS will be checked and tuning parameters will be validated post synchronization at Kasba 220 KV. In case of any delay in Synchronization of CESC System at 220 KV with Kasba S/S, revised timeline for field testing of PSS and UEL may be decided after discussion in appropriate forum.

**Islanding Operation**

1. PFR testing of BBGS Units will be carried out in February, 2022.
2. 'Islanded' signal will be incorporated in BBGS Unit 3 DCS for RGMO - FGMO switchover and performance will be checked. This trial will be given after PFR testing.

**ERLDC Request**

1. Study regarding PSS and UEL of BBGS needs to be done considering connectivity at 220 kV level as well 132 kV level separately in view of operating scenario during any contingency – CESC will revert.

2. Study needs to be done to ascertain whether 150 ms time delay in Islanding Scheme of CESC can be increased post Synchronisation at Kasba 220 KV, considering the Critical Clearing Time of BBGS Units – Study will be done by CESC.

3. A single combined ‘Load of CESC’s Islanded System’ (from Substations level) to be calculated and made available to ERLDC for enabling them to display in their SCADA – Feasibility will be checked by CESC.

4. Direct access to PMU at BBGS and EMSS to be provided to ERLDC for monitoring and analysis of islanding condition – Feasibility will be checked by CESC.

## Annexure C.4

ISTS	
Name of the element	Length (km)
400 kV Durgapur-Bidhannagar D/c	11
400 kV Rangpo-Teesta V-D/c	11.6
400 kV Teesta-III- Dikchu	15.1
400 kV Gaya-Chandauti D/c	17.36
220 kV Subhashgram-Subhashgram (WB) D/c	1
220 kV Dalkhola-Dalkhola (WB)-D/c	1.1
220 kV Alipurduar-Alipurduar (WB) D/c	6.34
220 kV Rajarhat-NewTown D/c	7.5
220 kV Binaguri-NJP D/c	9
220 kV Rourkela-Tarkera D/c	15.3
Odisha	
Name of the element	Length (km)
400 kV Indravati-Indravati (Gridco)	3.7
400 kV Meramundali GMR T/c	8
400 kV New Duburi-TSL D/c	8.65
220 kV Chandka-Chandka B	1
220 kV Rengali-Rengali D/c	1
220 kV Balimela-Balimela T	1.38
220 kV Meramundali-BSL D/c	2.4
220 kV Bolangir-New Bolangir D/c	2.8
220 kV Tarkera-RSP D/c	4.07
220 kV Sterlite-Vedanta D/c	4.15
220 kV New Duburi-Jindal Steel D/c	4.8
220 kV Rengali-Rengali PH D/c	5
220 kV Mendhasal-Infocity	5.5
220 kV Katapalli-Hindalco D/c	5.5
220 kV Jaynagar-Upper Kolab D/c	6
220 kV Mendhasal-Chandaka D/c	7
220 kV Keonjhar-Keonjhar D/c	7.48
220 kV Jeypore-Jaynagar D/c	7.7
220 kV New Duburi-TSL D/c	8.65
220 kV Jeypore-Jaynagar D/c	8.8
220 kV Tarkera-RSP D/c	10.2
220 kV Bidansi-Cuttack D/c	10.42
220 kV Jaypatna-Indravati	11.13
220 kV Meramundali-TTPS D/c	11.2
220 kV Meramundali-NALCO D/c	11.5
220 kV Joda-Jindal	14.6
220 kV Mendhasal-Atri	15
220 kV TSTPP-Rengali PH	16.78
West Bengal	
Name of the element	Length (km)
400 kV PPSP-New PPSP D/c	2
220 kV Kasba-Eastern Metropolitan	1
220 kV New Haldia-IPCHL D/c	2.7
220 kV Bidhannagar-DPL D/c	8
220 kV Bakreswar-Sadaipur D/c	8
220 kV Eastern Metropolitan-Princep Street	8.2
220 kV Domjur-New Chanditala D/c	8.32
220 kV New Cossipore-Princep Street	8.8
220 kV NewTown-CLC Bantala	13
220 kV Sagardighi-New Sagardighi D/c	14.38
220 kV Subhashgram-CLC Bantala	15
220 kV Domjur-Foundry Park D/c	15
220 kV New Cossipore-Eastern Metropolitan	16.2
220 kV Jeerat-Dharampur D/c	17

Bihar	
Name of the element	Length (km)
220 kV Patna-Sipara-3	0.3
220 kV Patna-Sipara-D/c	0.45
220 kV Purnea-New Purnea D/c	2
220 kV Darbhanga-Darbhanga (DMTCL) D/c	2.9
220 kV Kishanganj-Kishanganj Q/c	4.4
220 kV Pusauli-New Sasaram (Nadokhar) D/c	6.98
220 kV Gaya-BodhGaya D/c	8.5
220 kV Barauni (BTPS)-Mokama D/c	11.65
220 kV Barauni (BTPS)-Begusarai D/c	15
220 kV Muzaffarpur-MTPS D/c	17
220 kV Gaya-Chandauti D/c	18
DVC	
Name of the element	Length (km)
220 kV Durgapur-Parulia (DVC) D/c	1
220 kV Burnpur-IISCO D/c	1.2
220 kV Chandrapura-Chandrapura-1	1.5
220 kV Chandrapura-Chandrapura-2	3.5
220 kV Parulia (DVC)-Tamlra DSP T/c	6
220 kV Maithon-Kalyaneshwari D/c	7.6
220 kV Chandrapura-BSL	9
220 kV Chandrapura-MSMDBSL D/c	10
220 kV Waria-DSTPS D/c	11.14
220 kV Parulia (DVC)-Muchipara D/c	14.75
220 kV Mejia-Barjora D/c	16.7
220 kV Waria-Bidhannagar D/c	17.2
220 kV Parulia (DVC)-DSTPS D/c	17.34
Jharkhand	
Name of the element	Length (km)
220 kV Chaibasa-Chaibasa (JUSNL) D/c	0.7
220 kV Ranchi-Hatia	6
IPP	
Name of the element	Length (km)
400 kV Adhunik (APNRL)-Jamshedpur D/c	0.3
400 kV Sterlite-Lapanga D/c	18.64
220 kV Rangpo-Rongnichu D/c	7.26