





Tel No.:033-24235199, 24235005 FAX No.:033-24221802, 24221358 Web: www.erpc.gov.in

NO. ERPC/PROTECTION/2016-17/

DATE: 05.04.2017

FAX MESSAGE NO. -

Τo,

As per list enclosed.

Sub: Notice for 54th Protection Coordination sub-Committee (PCC) meeting of ERPC

Notice is hereby given that 54th PCC meeting of ERPC will be held on 20th April 2017 (Thursday) at 11: 00 hrs at ERPC Conference Room, Kolkata.

The tentative agenda items for discussion will be as follows:

- 1) Confirmation of the minutes of 53rd Protection sub-Committee Meeting of ERPC
- 2) Follow-up action on decision of previous Protection sub-Committee Meetings
- 3) Analysis of following grid disturbances of March, 2017:
- Disturbance at 400/220 kV Biharsharff S/s on 03-03-17 at 13:25 hrs.
- Disturbance at 400/220 kV Biharsharff S/s on 04-03-17 at 13:21 hrs.
- Disturbance at 400kV Vedanta S/s on 17-03-17 at 10:22 Hrs.
- Disturbance at 400kV Bakreswar S/s on 29-03-17 at 09:32 Hrs.
- Disturbance at 220kV Arrah S/s on 30-03-17 at 13:55 Hrs.
- 4) Multiple elements tripping without load loss:
- Disturbance at 400 kV RTPS (DVC) S/s on 30-03-17 at 11:54 Hrs.
- 5) Single line tripping incidences as per list enclosed at **Annexure-I**.

You are requested to kindly furnish the detail report along with all records (SLD, SOE, DR, Relay and schematic diagram of auxiliary supply, wherever applicable) related to above trippings for meaningful analysis during the meeting.

Your participation in the meeting is highly solicited. Please confirm your participation in the meeting along with name and designation of the participants.

Yours faithfully,

-sd-(A. K. Bandyopadhyaya) Member Secretary

Chief Engineer Trans (O.G.M)	Electrical Superinter din a Engineer (CDITL)
Chief Engineer, Trans (O&M) Biber State Electricity Board - Vident Blower	Electrical Superintending Engineer (CRITL)
Bihar State Electricity Board, Vidyut Bhawan,	Bihar State Electricity Board, Vidyut Bhawan,
Bailey Road, Patna-800021	Bailey Road, Patna-800021
Chief Engineer (SLDC)	Chief Engineer (CTC)
Damodar Valley Corporation, GOMD-I Premises,	Damodar Valley Corporation, P.O. Maithon Dam,
P.O Danesh Seikh Lane, Howrah- 711109	Dist. Dhanbad, Jharkhand-828207
Chief Engineer, Trans (O&M)	Electrical Superintending Engineer (CLD)
Jharkhand State Electricity Board	Jharkhand State Electricity Board, Kusai Colony,
Kusai Colony, Doranda, Ranchi-834002	Doranda, Ranchi-834002
Chief General Manager (O&M),	Sr. General Manager (PPA), Technical Wing,
OPTCL, Janpath, Bhubaneswar,	OHPCL, Orissa State Police Housing & Welfare
Odisha – 751 022. FAX: 0674-2542932	Corpn. Bldg. Vanivihar Chowk,
cgm.onm@optcl.co.in	Janpath,Bhubaneswar-752022
Chief Load Dispatcher, SLDC	Chief Engineer (Testing), WBSETCL
OPTCL, P.O. Mancheswar Rly. Colony	Central Testing Laboratory, Abhikshan, Salt Lake,
Bhubaneswar-751017	Kolkata-700091 (Fax no. 2367-3578/1235)
Chief Engineer (CLD)	Addl. Chief Engineer (ALDC)
WBSETCL, P.O. Danesh Sheikh Lane,	West Bengal Electricity Distribution Company Ltd
Andul Road, Howrah-711109	Vidyut Bhavan, 7 th Floor, Bidhannagar, Sector-I
	Salt Lake City, Kolkata-700091(Fax-033-2334-5862)
Dy. Chief Engineer (Testing)/ Sr. Manager (Testing)	General Manager (O&M)
CESC Ltd.,4, Sasi Sekhar Bose Road,	KhSTPS, NTPC Ltd., P.O. Deepti Nagar,
Kolkata-700025	Dist. Bhagalpur, Bihar-813203
General Manager(O&M)	Dy. General Manager (Engineering),
FSTPS, NTPC Ltd., P.O. Nabarun,	WBPDCL,OS Dept. Corporate Office, 3/C,L.A Block,
Dist. Murshidabad, West Bengal-742236	Salt Lake-III, Kolkata-700098 (Fax-033-23350516)
General Manager (O&M)	General Manager (OS), ERHQ-II, NTPC Ltd., 3 rd flr.
Barh STPS, NTPC Ltd., P.O. NTPC Barh,	OLIC Building, Plot no. N 17/2, Nayapalli, Unit-8
Dist. Patna, Bihar-803213	Bhubaneswar- 751012 (Fax No. 0674-2540919)
General Manager(O&M)	General Manager (O&M)
TSTPS, NTPC Ltd.	POWERGRID, Odisha Projects
P.O.Kaniha, Dist. Angul, Orissa-759117	Sahid Nagar, Bhubaneswar – 751 007
General Manager(OS), ERHQ-I, NTPC Ltd.,	Director (GM Division)
Loknayak Jaiprakash Bhawan, (2 nd Floor),	Central Electricity Authority
Dak Bunglow Chawk, Patna-800001	Sewa Bhawan, R. K. Puram, New Delhi-110066
Executive Director (O&M)	Electrical Superintending Engineer, TTPS,
NHPC Ltd., NHPC Office Complex, Sector-33,	Tenughat Vidyut Nigam Ltd.,
Faridabad, Haryana-121003 (Fax-01292272413)	Lalpania, Dist. Bokaro, Jharkhand-829149
Dy. General Manager (Electrical)	General Manager (OS), ER-I
IB Thermal Power Station, OPGCL	Power Grid Corporation of India Ltd.,
Banhapalli, Dist. Jharsuguda-768234, Orissa	Alankar Place, Boring Road, Patna-800001
Chief Engineer (Trans.)	Sr. Manager (CTMC)
Power Deptt., Govt. of Sikkim,	Durgapur Projects Limited,
Gangtok-731010	Durgapur-713201
General Manager,	Manager (Electrical), Adhunik Power & Natural
ERLDC, POSOCO	Resources Ltd. "Lansdowne Towers, Kolkata-700020
14, Golf Club Road, Tollygunge,Kolkata-700033	(Fax No. 033-2289 0285)
General Manager (OS), ER-II	Shri A.K.Nayak/Shri Sumit S Ghosh
Power Grid Corporation of India Ltd.,	Maithon Power Limited, Maithon Office, MA 5
J-I-15, Block-EP, Sector-V,Salt Lake,Kolkata-91	Gogna, Dist. Dhanbad, Jhankand State, PIN-828207
General Manager (P&O), PTC Ltd.,	Vice President, Vedanta Ltd.
Kanchanjunga Bldg.,18, Barakhamba Road,	1 st Floor, Module C/2, Fortune Tower, C S Pur,
New Delhi-110001	Bhubaneswar- 751023
Managing Director, Bhutan Power Corporation	Managing Director, Druk Green Power Corprn.
Post Box no. 580, Thimpu, Bhutan.	P.O. Box-1351, Thimpu, Bhutan.
ASSISTANT SECRETARY, ERPC	

Annexure-I

3 400 KV BAKERSWAR - ARAMBAG 29.03.16 09:32 29.03.17 13:20 DURING EMERGENCY S/D OF 400 KV MAIN BREAKER OF GT - II DUE TO LOW OIL DUE TO LOW OIL DUE TO LOW OIL PRESSURE PRESSURE PRESSURE SUBJECT STRATE SAME THE SUBJECT STRATE SAME SAME SAME SAME SAME SAME SAME SAM	Allier													
1 MAXAMPANALIZE_ADDATES 17.0.3.17 19.30 B.N. FAULT 2000 Approx PALZ H_7/2 Z JANA PASS TO VISION PASS TO VISION PARAMETER No. No. No. No. No. 2 0x00000000000000000000000000000000000	S.NO	LINE NAME	TRIP DATE	TRIP TIME	DATE	TIME	Reason	Clearance time in msec	LOCAL END	REMOTE END		received within 24	received after 24	Remarks
1 abiversection 10.01.7 19.30 BA NAULT approx Immon Binaguin Vet to be reached observed in PMU data No No No 2 description 20.01.77 13.30 28.01.77 14.02 B-N FAULT 100 M-NO No No No No No No No No No 100/220 HT - H A FAULT 100 No	Fault clearing time is violating protection standard (As per PMU data)													
2 1 20.03.1 13.08 22.03.1 14.92 E.H FAUL BAUSALTO AT BUSALTO	1	400 KV BINAGURI - MALBASE	17.03.17	19:05	17.03.17	19:30	B-N FAULT			Yet to be received		No	No	
3Interval3SolutionSolu	2		28.03.17	13:08	28.03.17	14:02	B-N FAULT					No	No	
1 220.V BMACHAGRAPHIC. CLAMMELSC 10.03.17 15.01 10.03.17 15.01 10.03.17 15.37 B-N FAULT <100 B-N, Z-L, O/C, 16.5 km from kA B-N, Z-L, 31.79 km from Chandil, F/C 2.325 kA No autoreclose operation observed in PMU data Viss 400/220 V(T-1 & Li along with directional O/C + 2.67 / 100 operation operation operation operation 2 200V BMACHAGEAPHIC. CLAMMELSC 27.03.17 17.01 28.03.17 12.47 R-Y FAULT 350 ms approx R-Y, ZL, F/C - 9.3 KA, 1.2 km from Rangpo Vist to be received No autoreclose operation observed in PMU data No 400/220 V(T-1 & Li along with operation operation operation No 400/220 V(T-1 & Li along with operation Vist to be received No autoreclose operation observed in PMU data No 400/220 V(T-1 & Li along with operation Mission operation operation No 400/220 V(T-1 & Li along with operation No Mission operation Mission operat	3	400 KV BAKERSWAR - ARAMBAG	29.03.16	09:32	29.03.17	13:20	BUS - I AT BAKRESWAR DURING EMERGENCY S/D OF 400 KV MAIN BREAKER OF GT - II DUE TO LOW OIL		Yet to be received	Yet to be received		<u>No</u>	No	tripped during the incident. On 13 02-17 at 09:55 hrs. LBB operated at Bakreswar Bus - I due to mal- operation. At that time, all elements at 220 kV level tripped
1 220.V BMACHAGRAPHIC. CLAMMELSC 10.03.17 15.01 10.03.17 15.01 10.03.17 15.37 B-N FAULT <100 B-N, Z-L, O/C, 16.5 km from kA B-N, Z-L, 31.79 km from Chandil, F/C 2.325 kA No autoreclose operation observed in PMU data Viss 400/220 V(T-1 & Li along with directional O/C + 2.67 / 100 operation operation operation operation 2 200V BMACHAGEAPHIC. CLAMMELSC 27.03.17 17.01 28.03.17 12.47 R-Y FAULT 350 ms approx R-Y, ZL, F/C - 9.3 KA, 1.2 km from Rangpo Vist to be received No autoreclose operation observed in PMU data No 400/220 V(T-1 & Li along with operation operation operation No 400/220 V(T-1 & Li along with operation Vist to be received No autoreclose operation observed in PMU data No 400/220 V(T-1 & Li along with operation Mission operation operation No 400/220 V(T-1 & Li along with operation No Mission operation Mission operat														
2 220EV BANGPO - NEV MELLI - 1 27.03.17 17.01 28.03.17 12:47 R-Y FAULT 350 ms from Rangpo resting from Rangpo resting from Rangpo resting resting for 220 kV Rangpo resting attempted	1		10.03.17	15:01	10.03.17	15:37			B-N, Z-I, O/C, 16.5 km from Ramchandrapur, F/C 2.32	B-N, Z-I, 31.79 km from	-	<u>Yes</u>	<u>Yes</u>	directional O/C & E/F) tripped from 220 kV side due to VAJ
A HYDC SASARAM 30.03.17 13:51 30.03.17 13:52 CONVERTOR CONTROL PROTECTION OPERATED Yet to be received Yet to be received No No 1 400KV ANGULJITPL-1 07.03.17 22:55 08.03.17 09:05 SPURIOUS TRIPPING DT received Did not trip Yes 2 400KV JEERAT- BAKRESWAR 13.03.17 03:48 13.03.17 04:22 SPURIOUS TRIPPING DT Received Did not trip No 3 400KV JEERAT- BAKRESWAR 13.03.17 03:48 13.03.17 04:22 SPURIOUS TRIPPING DT Received Did not trip No 3 400KV TALA - BINAGURI-HI 21.03.17 22:42 21.03.17 23:31 SPURIOUS TRIPPING Did not trip Yet to be received No 4 765 KV GAYA-BALIA SVC 24.03.17 13:50 SPURIOUS TRIPPING DT received Yet to be received No	2	220KV RANGPO - NEW MELLI - I	27.03.17	17:01	28.03.17	12:47	R-Y FAULT			Yet to be received		No	No	tripped at same time (R-B, Z-I, 0.73 km from Rangpo, F/C 5.3 kA). Charging attempted for 220 kV Rangpo - New Melli S/C at
4HVDC SASARAM30.03.1713:5130.03.1716:52CONTROL< PROTECTION OPERATEDYet to be receivedYet to be receivedNoNoNoNoVolta SaraamVolta Saraam30.03.1713:5130.03.1716:52CONTROL PROTECTION OPERATEDVolta SaraamVolta SaraamVolta SaraamNoNoNoNoNoNo1400KV ANGULJITPLI07.03.1722:5508.03.1709:05SPURIOUS TRIPPINGDT receivedDid not tripYes2400KV JEERAT - BAKRESWAR13.03.1703:4813.03.1704:22SPURIOUS TRIPPINGDT ReceivedDid not tripNo3400KV TALA - BINAGURH21.03.1722:4221.03.1723:31SPURIOUS TRIPPINGDid not tripYet to be receivedNoNo4265 KV GAYA-BALA SYC24.03.1713:50SPURIOUS TRIPPINGDT receivedYet to be receivedNoNo	3	400KV BIHARSARIF-SASARAM-II			30.03.17	16:02	O/V TRIPPED		Yet to be received	Yet to be received		No	No	
1 400KV ANGUL-JITPL-1 07.03.17 22:55 08.03.17 09:05 SPURIOUS TRIPPING DT received Did not trip Yes 2 400KV JEERAT - BAKRESWAR 13.03.17 03:48 13.03.17 04:22 SPURIOUS TRIPPING DT Received Did not trip No 3 400KV TALA - BINAGURI-II 21.03.17 22:42 21.03.17 23:31 SPURIOUS TRIPPING Did not trip Yet to be received No 4 765 KV GAYA-BALIA S/C 24.03.17 13:50 SPURIOUS TRIPPING DT received Yet to be received No	4	HVDC SASARAM	30.03.17	13:51	30.03.17	16:52	CONTROL PROTECTION		Yet to be received	Yet to be received		No	No	
2400KV JEERAT - BAKRESWAR13.03.1703:4813.03.1704:22SPURIOUS TRIPPINGDT ReceivedDid not tripNo3400KV TALA - BINAGURI-II21.03.1722:4221.03.1723:31SPURIOUS TRIPPINGDid not tripYet to be receivedNo4765 KV GAYA-BALIA S/C24.03.1713:2524.03.1713:50SPURIOUS TRIPPINGDT receivedYet to be receivedNo	Fault Not observed in PMU data													
A C <thc< th=""> <thc< th=""> <thc< th=""></thc<></thc<></thc<>	1	400KV ANGUL-JITPL-I	07.03.17	22:55	08.03.17	09:05	SPURIOUS TRIPPING		DT received	Did not trip		<u>Yes</u>		
4 765 KV GAYA-BALIA S/C 24.03.17 13:25 24.03.17 13:50 SPURIOUS TRIPPING DT received Yet to be received No No	2	400KV JEERAT - BAKRESWAR	13.03.17	03:48	13.03.17	04:22	SPURIOUS TRIPPING		DT Received	Did not trip		No		
	3	400KV TALA - BINAGURI-II	21.03.17	22:42	21.03.17	23:31	SPURIOUS TRIPPING		Did not trip	Yet to be received			No	
5 400 KV FARAKKA-KAHALGAON-1 25.03.17 09:40 25.03.17 10:30 SPURIOUS TRIPPING Yet to be received DT received No No	4	765 KV GAYA-BALIA S/C	24.03.17	13:25	24.03.17	13:50	SPURIOUS TRIPPING		DT received	Yet to be received		No	No	
	5	400 KV FARAKKA-KAHALGAON-I	25.03.17	09:40	25.03.17	10:30	SPURIOUS TRIPPING		Yet to be received	DT received		No	No	

S.NO	LINE NAME	TRIP DATE	TRIP TIME	RESTORATION DATE	RESTORATION TIME	Reason	Fault Clearance time in msec	Relay Indication LOCAL END	Relay Indication REMOTE END	Auto Recloser status	DR/EL received within 24 Hrs	DR/EL received after 24 Hrs	Remarks
	No autorecloser operation observed in PMU data												
1	400KV BARIPADA-KEONJHOR	05.03.17	16:34	06.03.17	10:27	B-N FAULT	<100	B-N, Z-I, F/C 1.34 KA, 2.104 km from Baripada, A/R unsuccessful due to DT received	B-N, Z-I, DT sent due to O/V in R & Y phases	No autoreclose operation observed in PMU data	<u>No</u>	No	B phase insulator puncher at LOC no. 48 (2.10km from Baripada), A/R started at Baripada end but failed due to DT receipt
2	400KV NEW PURNEA- KISHANGUNJ - I	10.03.17	03:11	10.03.17	03:41	B-N FAULT	<100	Yet to be received	Yet to be received	No autoreclose operation observed in PMU data	No	No	
3	400KV NEW PURNEA- MUZZAFFARPUR-I	10.03.17	06:15	10.03.17	06:37	B-N FAULT	<100	Yet to be received	Yet to be received	No autoreclose operation observed in PMU data	No	No	
4	400KV CHAIBASA-ROURKELA-I	10.03.17	13:24	10.03.17	14:03	Y-N FAULT	<100	Y-N, Z-I, F/C 2.61KA, 99 KM from Chaibasa	Y-N, Z-I, Carrier received, F/C 3.2 kA, O/V start	No autoreclose operation observed in PMU data	No	<u>Yes</u>	
5	400KV KOLAGHAT-KHARAGPUR-I	10.03.17	14:27	10.03.17	15:37	B-N FAULT	<100	B-N, Z-I, F/C 5.764 kA, 33.67 km from KTPP, A/R started but after 80 ms it got blocked	B-N, Z-I, Carrier received, DT received, 65.59 km from KGP, F/C 1.776kA	No autoreclose operation observed in PMU data	<u>Yes</u>	No	Reason for blocking of A/R at KTPP end may be explained
6	<u>400 KV BARH - KAHALGAON - I</u>	26.03.17	21:06	26.03.17	22:40	Y-N FAULT	<100	Y-N, Z-I, 4.78 km from Barh, F/C - 21 kA	A/R successful	No autoreclose operation observed in PMU data	No	No	Successful at KhSTPP end
7	400KV ANDAL-JAMSHEDPUR-I	27.03.17	19:35	28.03.17	20:47	R-N FAULT	<100	Yet to be received	Yet to be received	No autoreclose operation observed in PMU data	No	No	Line was under s/d. during charging attempt, line tripped again due to CB problem at Jamshedpur.
8	400KV ANDAL - RTPS-I	28.03.17	13:57	28.03.17	14:43	B-N FAULT	<100	B-N, 78.2 km from Andal, Carrier Received	B-N, Z-I, 13.4km from RTPS	No autoreclose operation observed in PMU data	No	No	
9	<u>400 KV ALIPURDUAR -</u> BONGAIGAON - I	30.03.17	11:20	30.03.17	12:11	Y-N FAULT	<100	Y-N, F/C 1.75 kA	Y-N, F/C 1.37 kA, 92 km from Bongaigaon, A/R successful	No autoreclose operation observed in PMU data	No	No	Successful at Bongaigaon end