

## भारत सरकार Govemment of India विद्युत मंत्रालय Ministry of Power **पूर्वी क्षेत्रीय विद्युत समिति**



**DATE: 05.11.2018** 

## Eastern Regional Power Committee

14, गोल्फ क्लब रोड, टालीगंज, कोलकाता-700033 14 Golf Club Road, Tollygunj, Kolkata-700033

Tel No.:033-24239651, 24239651, FAX No.:033-24239652, 24239653 Web: www.erpc.gov.in

NO. ERPC/PROTECTION/2018/

## FAX MESSAGE NO. -

To,

As per list enclosed.

Sub: Notice for 73<sup>rd</sup> Protection Coordination sub-Committee (PCC) meeting of ERPC

Notice is hereby given that 73<sup>rd</sup> PCC meeting of ERPC will be held on 29<sup>th</sup> November 2018 (Thursday) at 10: 30 hrs at ERPC Conference Room, Kolkata.

The tentative agenda items for discussion will be as follows:

- 1) Confirmation of the minutes of 72<sup>nd</sup> Protection sub-Committee Meeting of ERPC
- 2) Follow-up action on decision of previous Protection sub-Committee Meetings
- 3) Analysis of following grid disturbances of October, 2018:

SI No	Date	Time	Affected System	Summary	Load loss (MW)	Gen loss (MW)	Fault duration (As Per PMU)
1	01-10- 2018	15:41	ISTS	At 15:41 hrs, 400 kV Binaguri - Rangpo - I tripped on R-N fault resulting generation loss at Teesta III, Jorethang, Dikchu, Chujachen and Tashiding due to operation of SPS - I at Rangpo.	0	856	1.2 sec
2	03-10- 2018	17:23	JUSNL	220 kV PTPS - Hatia D/C were under shutdown. 220 kV Hatia - Ranchi D/C tripped from Hatia end due to suspected bus fault at Hatia	200	52	Fault not observed in PMU
3	04-10- 2018	00:18	JUSNL	220 kV PTPS - Hatia D/C were under shutdown. 220 kV Hatia - Ranchi D/C tripped from Hatia end due to suspected bus fault at Hatia	130	52	Fault not observed in PMU
4	07-10- 2018	16:56	ISTS	220 kV Purnea - Purnea D/C and 220 kV Purnea - Dalkhola D/C tripped due to Y phase CVT failure of 220 KV Purnea - I at Purnea Old end	160	0	600 ms
5	20-10- 2018	09:48	BSPTCL	220 KV New Purnea-Madhepura I was kept open due to high voltage condition. At 09:48 hrs 220 kV Purnea - Madhepura - II tripped on R-N fault resulting total power failure at Madhepura.	62	0	560 ms approx

SI No	Date	Time	Affected System	Summary		Gen loss (MW)	Fault duration (As Per PMU)
6	27-10- 2018	10:24	TPTL	At 10:24 Hrs, 220 KV TLDP-III – NJP tripped due to Y-B-N fault leading to tripping of all 4 units at TLDP III due to loss of evacuation path	0	134	<100 ms
7	31-10- 2018	23:52	ISTS	During PLCC testing of new 765kV Sundargarh-Dharamjaygarh Ckt-4, 765KV Bus-2 along with following 765KV elements connected with the Bus were tripped at 23:52 hrs of 31.10.2018 due to mal-function of Tie LBB relay of 765KV Angul Ckt-1. 1. 765KV 240MVAR Bus reactor-1 2. 765KV 240MVAR Bus reactor-2 3. 765KV Sundargarh-Angul Ckt-1 4. 765KV Sundargarh-darlipali(NTPC) Ckt-1 5. 765KV Sundargarh-darlipali(NTPC) Ckt-2	0	0	Fault not observed in PMU

4) Single line tripping incidences of October-2018 is enclosed at **Annexure-I**.

You are requested to kindly furnish the detail report along with all records (SLD, SOE, DR, Relay and schematic diagram of auxiliary supply, wherever applicable) related to above trippings for meaningful analysis during the meeting. You are also requested to upload the details in on-line tripping incident reporting system implemented in Protection Database Management System <a href="https://www.erpc-protectiondb.in">www.erpc-protectiondb.in</a>.

Your participation in the meeting is highly solicited. Please confirm your participation in the meeting along with name and designation of the participants.

Yours faithfully,

-Sd-(J. Ganeswara Rao) Executive Engineer

Chief Engineer, Trans (O&M)	Electrical Superintending Engineer (CRITL)
Bihar State Power Transmission Limited, Vidyut	Bihar State Power Transmission Limited, Vidyut
Bhawan, Bailey Road, Patna-800021	Bhawan, Bailey Road, Patna-800021
Chief Engineer (SLDC)	Chief Engineer (CTC)
Damodar Valley Corporation, GOMD-I Premises,	Damodar Valley Corporation, P.O. Maithon Dam,
P.O Danesh Seikh Lane, Howrah- 711109	Dist. Dhanbad, Jharkhand-828207
Chief Engineer, (CRITL)	Electrical Superintending Engineer (CLD)
Jharkhand Urja Sancharan Nigam Limited	Jharkhand Urja Sancharan Nigam Limited,
Kusai Colony, Doranda, Ranchi-834002	Kusai Colony, Doranda, Ranchi-834002
Chief General Manager (O&M),	Sr. General Manager (PPA), Technical Wing,
OPTCL, Janpath, Bhubaneswar,	OHPCL, Orissa State Police Housing & Welfare
Odisha – 751 022. FAX: 0674-2542932	Corpn. Bldg. Vanivihar Chowk,
cgm.onm@optcl.co.in	Janpath,Bhubaneswar-752022
Chief Load Dispatcher, SLDC	Chief Engineer (Testing), WBSETCL
OPTCL, P.O. Mancheswar Rly. Colony	Central Testing Laboratory, Abhikshan, Salt Lake,
Bhubaneswar-751017	Kolkata-700091 (Fax no. 2367-3578/1235)
Chief Engineer (CLD)	Addl. Chief Engineer (ALDC)
WBSETCL, P.O. Danesh Sheikh Lane,	West Bengal Electricity Distribution Company Ltd
Andul Road, Howrah-711109	Vidyut Bhavan, 7 <sup>th</sup> Floor, Bidhannagar, Sector-I
	Salt Lake City, Kolkata-700091(Fax-033-2334-5862)
Dy. Chief Engineer (Testing)/ Sr. Manager (Testing)	General Manager (O&M)
CESC Ltd.,4, Sasi Sekhar Bose Road,	KhSTPS, NTPC Ltd., P.O. Deepti Nagar,
Kolkata-700025	Dist. Bhagalpur, Bihar-813203
General Manager(O&M)	Dy. General Manager (Engineering),
FSTPS, NTPC Ltd., P.O. Nabarun,	WBPDCL,OS Dept. Corporate Office, 3/C,L.A Block,
Dist. Murshidabad, West Bengal-742236	Salt Lake-III, Kolkata-700098 (Fax-033-23350516)
General Manager (O&M)	General Manager (OS), ERHQ-II, NTPC Ltd., 3 <sup>rd</sup> flr.
Barh STPS, NTPC Ltd., P.O. NTPC Barh,	OLIC Building, Plot no. N 17/2, Nayapalli, Unit-8
Dist. Patna, Bihar-803213	Bhubaneswar- 751012 (Fax No. 0674-2540919)
General Manager(O&M), TSTPS, NTPC Ltd.,	General Manager (O&M), POWERGRID, Odisha
P.O.Kaniha, Dist. Angul, Orissa-759117	Projects, Sahid Nagar, Bhubaneswar – 751 007
General Manager(OS), ERHQ-I, NTPC Ltd.,	Manager (Electrical), Adhunik Power & Natural
Loknayak Jaiprakash Bhawan, (2 <sup>nd</sup> Floor),	Resources Ltd. "Lansdowne Towers, Kolkata-700020
Dak Bunglow Chawk, Patna-800001	( Fax No. 033-2289 0285)
Executive Director (O&M)	Electrical Superintending Engineer, TTPS,
NHPC Ltd., NHPC Office Complex, Sector-33,	Tenughat Vidyut Nigam Ltd., Lalpania, Dist. Bokaro,
Faridabad, Haryana-121003 (Fax-01292272413)	Jharkhand-829149
Dy. General Manager (Electrical)	General Manager (OS), ER-I
IB Thermal Power Station, OPGCL	Power Grid Corporation of India Ltd.,
Banhapalli, Dist. Jharsuguda-768234,Orissa	Alankar Place, Boring Road, Patna-800001
Chief Engineer (Trans.)	Sr. Manager (CTMC)
Power Deptt., Govt. of Sikkim, Gangtok-731010	Durgapur Projects Limited, Durgapur-713201
Executive Director,	Head Construction, ENCIL, Siliguri-7340051
ERLDC, POSOCO, Tollygunge, Kolkata-700033	
General Manager (OS), ER-II	Shri A.K.Nayak/Shri Sumit S Ghosh
Power Grid Corporation of India Ltd.,	Maithon Power Limited, Maithon Office, MA 5
J-I-15, Block-EP, Sector-V,Salt Lake,Kolkata-91	Gogna, Dist. Dhanbad, Jhankand State, PIN-828207
General Manager (P&O), PTC Ltd.,	Vice President, Vedanta Ltd.
Kanchanjunga Bldg.,18, Barakhamba Road,	1 <sup>st</sup> Floor, Module C/2, Fortune Tower, C S Pur,
New Delhi-110001	Bhubaneswar- 751023
Managing Director, Bhutan Power Corporation	Managing Director, Druk Green Power Corprn.
Post Box no. 580, Thimpu, Bhutan.	P.O. Box-1351, Thimpu, Bhutan.
General Manager, Darbhanga(Bihar), Darbhanga	Shri Brajesh Kumar Pande, Plant Head, JITPL.

Motihari Transmission Company Limited (DMTCL)	(FAX:011-26139256-65)
Shri D. P. Bhagava, Chief Consultant (O&M), Teesta	Director (GM Division), Central Electricity Authority
Urja Limited, New Delhi (FAX:011-46529744)	Sewa Bhawan, R. K. Puram, New Delhi-110066
Director (NPC), CEA, NRPC Building, Katwaria	President, Dans Energy Pvt. Ltd, 5th Floor, DLF
Sarai, New Delhi- 110016	Building No. 8, Tower-C, Gurgaon - 722OO2
Director, Shiga Energy Pw. Ltd., 5th Floor, DLF	DGM (E&I), HALDIA ENERGY LIMITED, BARIK
Building No. 8, Tower-C, Gurgaon - 722OO2	BHAWAN, KOKATA-700072, FAX: 033-22360955

## CC:

ASSISTANT SECRETARY, ERPC	
ASSISTANT SECRETARY, EN	

									Annexure-
	List	t of line	tripping i	n the m	onth of October 20	018 which may be discussed	in PCC		
LINE NAME	TRIP DATE	TRIP TIME	RESTORATI ON DATE	RESTORA TION TIME	Relay Indication LOCAL END	Relay Indication REMOTE END	Reason	Fault Clearance time in msec	Remarks
		Misce	llaneou	ıs: Trip	ping on DT, N	o Fault observed in PN	ΛU		
100KV INDRAVATI(PG)-INDRAVATI(GR)-SC	10-10-2018	16:49	10-10-2018	17:47	OVERVOLTAGE TRIPPED AT GRIDCO END		OVERVOLTAGE TRIPPED AT GRIDCO END		PMU Voltage : 413 KV
00KV MALBASE-BINAGURI-I	13-10-2018	0:16	13-10-2018	0:38	Tripped only at Binaguri, DT received		DT received at Binaguri		No fayult observed in PMU
00KV BOLANGIR-ANGUL-SC	16-10-2018	2:54	16-10-2018	3:24	DT received at Bolangir	line did not trip from Angul	DT received at Bolangir		
00KV BOLANGIR-ANGUL-SC	16-10-2018	3:27	16-10-2018	5:17	DT received at Bolangir	line did not trip from Angul	DT received at Bolangir		No fayult observed in PMU
00KV ALIPURDUAR-BONGAIGAON-II	16-10-2018	10:44	16-10-2018	11:37	R-N Fault DT Recived		R-N Fault		No fayult observed in PMU
				<u>Aut</u>	oreclose relate	<u>ed issues</u>			
220KV JODA-RAMCHANDRAPUR-SC	02-10-2018	12:10	02-10-2018	12:36	Y-N,245 A,-1 km from joda	y-n,53.71 km,1.99 KA,o/c	Y-N Fault	< 100 msec	No A/R operation found in PMU
00KV ALIPURDUAR-BONGAIGAON-I	09-10-2018	9:07	09-10-2018	9:18	Z2 R-N ,FC 1.107 KA,FD not given	A/R successful,, Z1,R-N,3.39 KA,FD 30.49	R-N Fault	700 msec	No A/R operation found in PMU
OOKV KHARAGPUR-CHAIBASA-I	12-10-2018	13:02	12-10-2018	13:36	R-N, Z-1, 21.72km, 8.3 kA	A/R attempted at Chaibasa	R-N Fault	< 100 msec	No A/R operation found in PMU
00KV BARH-MOTIHARI-I	14-10-2018	10:32	14-10-2018	10:56		27.8 KM, BN, 3.3 KA	B-N Fault	< 100 msec	No A/R operation found in PMU
00kv kharagpur-chaibasa-ii	20-10-2018	11:02	20-10-2018	11:13	B_N Fault	A/R successful	B-N Fault	< 100 msec	No A/R operation found in PMU
220KV JODA-JINDAL-JAMSHEDPUR-I	22-10-2018	12:52	22-10-2018	13:17		BN, Z1, 49.27 KM	B-N Fault	< 100 msec	No A/R operation found in PMU
20KV PUSAULI-SAHUPURI-SC	23-10-2018	12:24	23-10-2018	13:53	R-N, 3.5KA, 40KM		R-N Fault	< 100 msec	No A/R operation found in PMU
20KV KATAPALLI-BOLANGIR(PG)-SC	23-10-2018	12:35	23-10-2018	13:12	B-N, 5.8KA		B-N Fault	< 100 msec	No A/R operation found in PMU
00KV BINAGURI-ALIPURDUAR-I	28-10-2018	11:20	28-10-2018	11:52			B-N Fault (As per PMU)	800 msec	No A/R operation found in PMU
00KV KHARAGPUR-CHAIBASA-I	29-10-2018	12:24	29-10-2018	12:36	Z1, RN, 25.1 KM, 7.29 KA, A/R L/O	RN, 1.70 KA, Z2, 173.5 KM	R-N Fault	< 100 msec	No A/R operation found in PMU