

भारत सरकार Government of India विद्युत मंत्रालय Ministry of Power **पूर्वी क्षेत्रीय विद्युत समिति** Eastern Regional Power Committee 14, गोल्फ क्लब रोड, टालीगंज, कोलकाता-700033 <u>14 Golf Club Road</u>, Tollygunj, Kolkata-700033



Tel No.:033-24239657, 24239650 FAX No.:033-24239652, 24239653 Web: www.erpc.gov.in

## NO. ERPC/PROTECTION/2021/439

DATE: 06/07/2021

Τo,

As per list enclosed,

## Sub: Notice for 104th Protection Coordination sub-Committee (PCC) meeting of ERPC

Sir,

Notice is hereby given that **104**<sup>th</sup> **PCC meeting** of ERPC will be held on **13.07.2021 (Tuesday)** from **10:30 hrs** through **online Microsoft Teams meeting platform**. The meeting link will be forwarded through e-mail or message. You are requested to enter the participant name and designation and organisation name while joining the meeting. The following coordinator may be contacted for any assistance:

Kumar Satyam, Asst. Director-II, ERPC, Mob: 7355225072, E-mail: satyam.24365@gov.in

The tentative agenda items for discussion will be as follows:

- 1) Confirmation of the minutes of 103<sup>rd</sup> Protection sub-Committee Meeting of ERPC.
- 2) Analysis of following grid disturbances of June 2021:
- Total Power Failure at 220 kV Sonenagar (BSPTCL) Substation on 01/06/2021 at 11:56 Hrs, 07/06/2021 at 13:15 Hrs, 21/06/2021 at 11:15 Hrs, 24/06/2021 at 13:42Hrs & 30/06/2021 at 19:13 Hrs and Disturbance on 25/06/2021 at 16:04 Hrs
- Total Power Failure at 220 kV Barauni (BSPTCL) Substation on 01/06/2021 at 17:03 Hrs
- Disturbance at 220 kV Biharsharif (BSPTCL) Substation on 01/06/2021 at 17:10 Hrs
- Disturbance at 220 kV Hazipur (BSPTCL) Substation on 09/06/2021 at 20:46 Hrs
- Total Power Failure at 220 kV Tashiding HEP on 25/06/2021 at 04:54 Hrs
- 3) Status of Implementation of Islanding Schemes in Eastern Region.
- 4) Follow up of decision of previous Protection Coordination sub-Committee Meetings.
- 5) Single line tripping incidences of transmission elements for the month of June 2021 as enclosed at Annexure-1.

You are requested to kindly furnish the detail report along with all records (SLD, SOE, DR, Relay and schematic diagram of auxiliary supply, wherever applicable) related to above trippings well in advance for meaningful analysis. You are also requested to upload the details in on-line tripping incident reporting system implemented in Protection Database Management System (<u>www.erpc-protectiondb.in</u>).

Your participation in the meeting is highly solicited.

Yours faithfully,

(D. K. Bauri) Superintending Engineer(O& PS )

	·
Chief Engineer, Trans (O&M)	Electrical Supeeerintending Engineer (CRITL)
Bihar State Power Transmission Limited,	Bihar State Power Transmission Limited,
VidyutBhawan, Bailey Road, Patna-800021	VidyutBhawan, Bailey Road, Patna-800021
Chief Engineer(System Operation), SLDC,	
BSPTCL, Patna-800021	
Chief Engineer (SLDC)	Chief Engineer (CTC)
Damodar Valley Corporation, GOMD-I Premises,	Damodar Valley Corporation, P.O. Maithon Dam, Dist.
P.O DaneshSeikh Lane, Howrah- 711109	Dhanbad, Jharkhand-828207
Chief Engineer, (CRITL)	Electrical Superintending Engineer (CLD)
Jharkhand UrjaSancharan Nigam Limited	Jharkhand UrjaSancharan Nigam Limited,
Kusai Colony, Doranda, Ranchi-834002	KusaiColony,Doranda, Ranchi-834002
Chief General Manager (O&M),	Sr. General Manager (PPA), Technical Wing,
OPTCL, Janpath, Bhubaneswar,	OHPCL, Orissa State Police Housing & Welfare Corpn.
Odisha – 751 022. FAX: 0674-2542932	Bldg. VaniviharChowk, Janpath, Bhubaneswar-752022
cgm.onm@optel.co.in	Blug. vanivinarChowk, Janpath, Bhubaneswai-752022
	ChiefEnsineer (Testing) WDSETCI
Chief Load Dispatcher, SLDC	Chief Engineer (Testing), WBSETCL
OPTCL, P.O. Mancheswar Rly. Colony	Central Testing Laboratory, Abhikshan, Salt Lake,
Bhubaneswar-751017	Kolkata-700091 (Fax no. 2367-3578/1235)
Chief Engineer (CLD)	Addl. Chief Engineer (ALDC)
WBSETCL, P.O.Danesh Sheikh Lane,	West Bengal Electricity Distribution Company Ltd
AndulRoad, Howrah-711109	VidyutBhavan, 7 <sup>th</sup> Floor, Bidhannagar, Sector-I
	Salt Lake City, Kolkata-700091(Fax-033-2334-5862)
Dy. Chief Engineer (Testing)/ Sr. Manager (Testing)	General Manager (O&M)
CESC Ltd.,4, SasiSekhar Bose Road,	KhSTPS, NTPC Ltd., P.O.Deepti Nagar,
Kolkata-700025	Dist. Bhagalpur, Bihar-813203
General Manager(O&M)	Dy. General Manager (Engineering),
FSTPS, NTPC Ltd., P.O. Nabarun,	WBPDCL, OS Dept. Corporate Office, 3/C, LA Block,
Dist. Murshidabad, West Bengal-742236	Salt Lake-III, Kolkata-700098 (Fax-033-23350516)
General Manager (O&M)	General Manager (OS), ERHQ-II, NTPC Ltd., 3 <sup>rd</sup> flr.
Barh STPS, NTPC Ltd., P.O. NTPC Barh,	OLIC Building, Plot no. N 17/2, Nayapalli, Unit-8
Dist. Patna, Bihar-803213	Bhubaneswar- 751012 (Fax No. 0674-2540919)
General Manager(O&M), TSTPS, NTPC Ltd.,	General Manager (O&M), POWERGRID, Odisha
P.O.Kaniha, Dist. Angul, Orissa-759117	Projects, Sahid Nagar, Bhubaneswar – 751 007
General Manager (OS), ERHQ-I, NTPC Ltd.,	Manager (Electrical), Adhunik Power & Natural
LoknayakJaiprakashBhawan, (2 <sup>nd</sup> Floor),	Resources Ltd. "Lansdowne Towers, Kolkata-700020
DakBunglowChawk, Patna-800001	(Fax No. 033-2289 0285)
Executive Director (O&M)	Electrical Superintending Engineer, TTPS,
NHPC Ltd., NHPC Office Complex, Sector-33,	TenughatVidyut Nigam Ltd.,Lalpania, Dist. Bokaro,
Faridabad, Haryana-121003 (Fax-01292272413)	Jharkhand-829149
Dy. General Manager (Electrical)	General Manager (OS), ER-I
IB Thermal Power Station, OPGCL	Power Grid Corporation of India Ltd.,
Banhapalli, Dist. Jharsuguda-768234, Orissa	Alankar Place, Boring Road, Patna-800001
Chief Engineer (Trans.)	Sr. Manager (CTMC)
Power Deptt., Govt. of Sikkim, Gangtok-731010	Durgapur Projects Limited, Durgapur-713201
Executive Director, EPL DC, POSOCO, Tellygunge, Kellyste 700022	ShriA.K.Nayak/ShriSumit S Ghosh
ERLDC, POSOCO, Tollygunge, Kolkata-700033	Maithon Power Limited, Maithon Office, MA 5 Gogna,
	Dist. Dhanbad, Jhankand State, PIN-828207
General Manager (OS), ER-II	Head – Regulatory and contracts, IndiGrid Limited
Power Grid Corporation of India Ltd.,	, 247 Embassy, Office No 107, 'B' Wing, Hindustan Co.
J-I-15, Block-EP, Sector-V,Salt Lake,Kolkata-91	Bus Stop, Gandhi Nagar, L.B.S. Road, Vikhroli West,
General Manager (P&O), PTC Ltd.,	Mumbai – 400 079. Ph : +91 845509 96408
Kanchanjunga Bldg.,18, Barakhamba Road,	
New Delhi-110001	

Managing Director, Bhutan Power Corporation	Managing Director, Druk Green Power Corprn.
Post Box no. 580, Thimpu, Bhutan.	P.O. Box-1351, Thimpu, Bhutan.
Associate Director (Commercial and Regulatory)	ShriBrajesh Kumar Pande, Plant Head, JITPL.
Darbhanga-Motihari Transmission Company Limited	(FAX:011-26139256-65)
(DMTCL),503, Windsor, Off CST Road, Kalina,	
Santacruz(E), Mumbai-400098	
Shri D. P. Bhagava, Chief Consultant (O&M),	Director (GM Division), Central Electricity Authority
TeestaUrja Limited, New Delhi (FAX:011-	SewaBhawan, R. K. Puram, New Delhi-110066
46529744)	
Director (NPC), CEA, NRPC Building,	President, Dans Energy Pvt. Ltd, 5th Floor, DLF
KatwariaSarai, New Delhi- 110016	Building No. 8, Tower-C, Gurgaon - 722002
Director, Shiga Energy Pw. Ltd., 5th Floor, DLF	DGM (E&I), HALDIA ENERGY LIMITED, BARIK
Building No. 8, Tower-C, Gurgaon - 722002	BHAWAN, KOKATA-700072, FAX: 033-22360955
President, TPTL, BhikajiCama Place, New Delhi,	
110066	

## Annexure 1

	L	ist of im	port	ant transi	mission	lines i	n ER	which tripped in J	UNE-2	202	1		
S.NO	LINE NAME	TRIP DATE	TRI P TIM E	Relay Indication LOCAL END	Relay Indicati on REMOT E END	Reaso n	Fault Clear ance time in msec	Remarks	DR CONFI GURAT ION DESCR EPANC Y	EIVE D FRO M	DR/E L RECE IVED FRO M REM OTE END	LOCAL END UTILITY	REMOTE END UTILITY
1	400KV- MUZAFFARPUR- GORAKHPUR-1	06-01-2021	02:03	MFR: B-N, 60.78Km, 5.4kA		B-Earth	<100	B phase fault and B phase MCB &TCB tripped .B phase MCB A/R successful after 1 seconds but at 1.2 seconds again fault in reclaim time and all 3phase MCB got opened but rest 2 phase TCB was closed and after 2 seconds B phase TCB reclosed and got failed and ,3 phase TCB opend .At the instance of fault in reclaim time all 3 phase MCB and TCB should have tripped,failing which caused repeated fault feeding .		YES	NO	PG-ER-1	
2	400KV-BINAGURI- ALIPURDUAR (PG)-1	06-01-2021	01:05	e		O/V STG-1	NA	At Apd end Y phase voltage was 16 Kv higher than rest two phases and at Binaguri end voltage was normal .So at APD end CVT neutral earthing may be checked and overall cvt may also be checked.		YES	YES	PG-ER-2	PG-ER-2
3	400KV-MAITHON- DURGAPUR-1	06-01-2021	15:51	MAITHON END:- R-N, 7.39KA, 38.6KM	DURGAPUR END:- R-N, 8.07KA, 31.9KM	R-Earth	<100	Seems 3 phase tripping from Maithon end while at Durgapur end 3 phase A/R after 1 second.		YES	NO	PG-ER-1	DVC
4	220KV-PUSAULI- DEHRI-1	06-01-2021	14:25	pusauli:- B-N FAULT 18.7KM 5.76KA	DEHRI-Z1, BN, 35.91km, 2.55KA	B-Earth	<100	No A/R attempted		NO	YES		BSPTCL
5	400KV-BARH- MOTIHARI-1	06-02-2021	20:49		Z1 Y-N FD- 22.7km FC- 7.57kA	Y-Earth	<100	At Barh end A/R attempted after 1.75 sec and got failed reason may be explained.		YES	NO	NTPC	DMTCL

		1			Баранда. Б. 14,			1			r	
	400KV-			Meeramundali: B-	19.22kM,			3 Phase tripping from Lapanga				
	MERAMUNDALI-			N, 1.95kA, 199km	14.4kA, A/R			end.Meramundali end A/R				
6	LAPANGA-2	06-05-2021	20:22		unsuccessful	B-Earth	<100	unsuccessful.	YES	YES	OPTCL	
	400KV-			Durgapur- Z1 B-N				· · ·				
	DURGAPUR-			FC-3.3kA FD-								
7	SAGARDIGHI-2	06-05-2021	17:33			B-Earth	800	on for delayed tripping may be explained.	NO	YES	PG-ER-2	WBPDCL
		00 05 2021	17.55	r		D Latu	000	on for delayed tripping may be explained.	110	1 LS	I O ER 2	WBIBCE
	400KV-			successful, R Ph, Z-								
_	BAHARAMPUR-				N, Z-1, 23 km,							
8	BHERAMARA-1	06-07-2021	15:58	KA,	5 kA	R-Earth	<100	A/R successful from Baharampur end only	y. YES	NO	PG-ER-2	
	400KV-LAPANGA-			Lapanga: Z-1, R-								
	OPGC (IB			Ph, 2.37kM,				3 PHASE TRIPPING from Lapanga				
9	THERMAL)-1	06-11-2021	15:54	If=25.52kA		R-Earth	<100	end .No A/R reason may be shared.	YES	NO	OPTCL	
	,			JSG: A/R								
	400KV-			successful, R-N,	OPGC: R-N,							
	JHARSUGUDA(GI			51.35Km, 6.5kA	3.6Km,			A/R successful from only				
10	S)-OPGC-1	06-12-2021	17:06	,	21.59kA	R-Earth	<100	Jharsuguda end.	YES	NO	PG-ER-3	OPTCL
10	3)-0100-1	00-12-2021	17.00		21.39KA	K-Ealui	<100	Jilaisuguda end.	11.5	NO	PG-ER-5	OPICL
				RB end- Z1 Y-n								
	400KV-MAITHON-			FD-17.4km FC-	Maith PG- AR							
11	MAITHON RB-1	15/06/2021	15:43	10.044kA	successful	Y-Earth	<100	A/R successful from PG end,	YES	NO	MPL	PG-ER-1
		15/00/2021	15.45	oonninnin n	5/10/11/01011	i Latti	<100	rin o phase red opend at bágraigin	125	110		I G ER I
				N, Z-1 , 25.41KM,	I:- Z-1. R-N,			end at the instance of fault ,while				
	400KV-GOKARNA-			10.24KA,	4.388KM,			only MCB R phase opend and ,A/R				
12	SAGARDIGHI-2	17/06/2021	13:11		15.28KA	R-Earth	<100	attempted and unsuccessful .	YES	YES	WBSETCL	WBPDCL
				Ranchi: Y_N, 15.8				Fault in z-1 from ranchi and z-2				
	220KV-CHANDIL-			KM, 6.1 kA,A/r				from chandil.Ranchi end sent carrier				
13	RANCHI-1	22/06/2021	12:59	successful from		Y-Earth	500	still chandil end tripped after z-2	YES	YES	JUSNL	PG-ER-1
					A/R							
	400KV-RANCHI-			Ranchi: B-N Fault,	SUCCESFUL			3 phase tripping from Ranchi				
	RAGHUNATHPUR			FD: 53km, FC:	AT RTPS			without A/R while RTPS end A/R				
15	2	24/06/2021	11:57	5.152 KA	END	B-Earth	<100	successful.	YES	NO	PG-ER-2	DVC
	220KV-NEW			New Melli: Y-B, Iy-								
	MELLI-			4.67kA, Ib-5.15kA,								
16	TASHIDING-1	25/06/2021	04:54	10Km	NA	Y-B-Earth	<100	Y-B Phase to phase fault .	YES	YES	PG-ER-2	DANS
								Y-B phase fault initially in z-2 of				
								rangpo sensing the fault of Thep-				
								new melli then same fault cleared				
								but again within few ms same YB				
								phase fault observed IN Z-1 and line				
					Y-B, Iv-			1				
	220KV-				, ,			tripped.Seems fault due to back				
					5.4kA, Ib-			flashover .High voltage in Y-B				
17	TASHIDING-	25/06/2021	04.54	V D ED 7 50V	5.2kA,	VDD 1	100	phases observed at the time of	VEG	VEC		
17	RANGPO-1	25/06/2021	04:54	Y-B, FD - 7.53Km	44.42Km	Y-B-Earth	<100	tripping. Fault in z-2 from purnea ,but carrier	YES	TES	PG-ER-2	
	220KV-NEW			NEW PURNEA: B-	<u>*</u>			-				
10	PURNEA-	26/06/2021	10.25	N, Z-1, FD:	N, Z1		500	not receipt from madhepura	VEG	VEC		DCDTCI
18	MADHEPURA-1	26/06/2021	10:35	82.7kM, FC:	,12.3km	B-Earth	500	although it was sent .Plcc	YES	TES	PG-ER-2	BSPTCL

	22011			DIMONIN						1			
	DARBHANGA			FAULT Y_N , FC -				A/R successful from DMTCL end					
19	(DMTCL)-	28/06/2021	11:40	14.47 KA , FD -		Y-Earth	<100	only.	N	0	NO	BSPTCL	
20	400KV-BINAGURI- ALIPURDUAR (PG)-1	29/06/2021	05:04	. Binaguri: DT Received	APD: O/V Stage 1, DT send	O/V STG-1	<100	At Apd end Y phase voltage was 16 Kv higher than rest two phases and at Binaguri end voltage was normal .So at APD end CVT neutral earthing may be checked and overall cvt may also be checked.	Ν	0	NO	PG-ER-2	
21	220KV- SITAMARHI- MOTIPUR-1	29-06-2021	08:56	Sitamaarhi: R-N, Fc= 6.78 kA, 16.1 km; tripped from Sitamarhi end only		R-Earth	350						
													1
													1
	1												
	1												
			1										
L	1												